

HTS-420R Total Station Manual

### **Preface**

Thanks a lot for purchasing our total station!

This manual is your good helper, please read it carefully before using the instrumentand keep it safely.

### Product affirms:

In order to get the best service from our company, please feedback your instruments' versionincludingnumber, purchasing date and your suggestions to us after the purchasing of the product.

We will attach great importance to any piece of advice from you,

We will be very concerned about any detail of our products,

We will make great efforts to provide better quality.

Notice: Our Company has the right to upgrade and improve the technical parameters of instruments, which may not be announced in advance. The pictures in the manual are only for reference and kind prevail.

### Features:

Rich Feature: Our Total Station is equipped with a wealth of measurement applications including data storage, parameter settings and other functions for a

### 1. Absolute coded dial

With absolute digital dial, instrumentscan be measureddirectlywhen it powers on. The measured azimuth angle result will not be lost even when the instrument shut off.

### 2. powerful memory management

Large-capacity EMS memory, easy to manage the file system, serving to add, delete and transfer data

### 3. No prism ranging

The series Total Station HTS-220R with laser ranging No-Prism is capable of surveying forlong distance, fast and precise measurements with various materials and different colors of objects (such as building walls, poles, wires, cliff wall, mountain, mud, stakes, etc.). For those which are hard or impossible to be reached, the application of Prism features can be a good measurement tasks.

### 4. special measurement procedure

The series total station is equipped with the basic surveying function as well as special measurement procedures, undertaking REM, offset measuring, stakeout, Resection, area measurement and calculation, road design etc. to meet the needs of professional measurement.

### 5. eyepiece changeable

The instruments' eyepiece can be changed, and equipped with a diagonal eyepiece, serving to observe zenith and high buildings

### 6. An optional laster plumb

The site features is easy to instruct and set up stations

### NOTE:

Avoid look directly into the sun with the eyepiece when measuring. Recommended to use solar filter to reduce the impact

- 1. Avoid extreme temperature when storing equipment and sudden changes in temperature when using the instrument.
- 2. The instrument should be loaded in boxplaced in dry and ventilated place and prevented from shock, dust and moisture when it is not in use.
- 3. In order to get good accuracy, you should leave the instrument in the box if the instrument temperaturehas large difference between working and storing you may unpack the box and employ the instrument until the instrument reaches the temperature at the working field.
- 4. If the instrument is not used for a long time, the battery should be unloaded and stored separately and charged once a monthto prolong battery life.
- 5. The instrumentshould be installed in box when it is transported. Extrusion, collision and violent vibration need to be carefully avoided during the transport process. The soft mat May be placed around the box on the long-distance transportation.
- 6. It is better to use high quality wooden foot stool to make surethe stability of measurement and improve its accuracy, whensetting up the instrument.
- 7. Only use absorbent cotton or lens paper towipe the instrument gentlylf exposed optical device need to be cleaned.
- 8. Use flannelette or hairbrush to clean the instrument after using. Do not electrify and start up after the device got wet in a rain. Using clean soft cloth to wipe it dry and put it at ventilated place for a period of time to make the instrument fully dry before using or packing.
- 9. Inspect instrument carefully and comprehensively to ensure its indicators, function, power supply, initial setting and correction parameters meet the requirements before operating.
- 10. If the function is abnormal, non-professional maintenance persons are not allowed to dismantle the device without authorization in case of any unnecessary damage.
- 11. Theemitted light of the no-prism total station HTS-220R is laser, do not direct to eyes.

### Security Guide

Pay attention to the following safety matters when you use the laser ranging free of prism.

### Warning:

Total station fit out laser level 3R/IIIa which is recognized by the loge, which is above:

the verticallocking screw saying: "3A laser product ".This product belongs to Class 3R levellaser .According to the following standards IEC 60825-1: 2001Class 3R/ $\mathbb{II}$  a laser product can reachfive times of emission limits of the Class 2/ $\mathbb{II}$  in the wavelength between 400nm-700nm.

### Warning:

Continuous stareinto the laser beam is harmful.

#### Prevention:

Do not stare at laser beam or point to others. The reflected beams is the effective signal of the instrument. It's safety to observe by eyepice.

### Warning:

When the laser beam is irradiated reflected by prisms, plane mirrors, surface of metal and windows,it's dangerous to look straightinto the reflected beams.

### Prevention:

Don't stare at the reflected beams. When the laser is switched on (distance mode), do not obstruct optical path or stand near the prism. Target at a prismwith total station telescope only.

### Warning:

It's dangerous to use the Class 3R laser deviceinproperly.

### **Prevention:**

Toavoid injury, each user must carry safety prevention measures and operate the instrument within the safety scope according to standard IEC60825-1: 2001).

The following is the explanation of the main part of the standard:

Class 3R level raserproducts are used outdoors and in construction (surveying with No-Prism).

A: Only trained and certified personnels are allowed to install, adjust and operate the laser equipment.

B: set up appropriate laser warning sign within the operating field

C: To prevent anyone from looking into the laser beam use an optical instrument to observe.

D: in order to prevent laser damage to persons, the laser beams should be blocked at the end of the working route, and also should be cut off when people work in the restricted area (harmfuldistance)where laser beams crossing are harmful.

E: the route of the laser beam must set to be higher or lower than the human eye.

F: properly store and safekeep the laser products when they it is not used, unauthenticated personals are not allowed using it.

G: Do not point laser beams at surfaces such as plane mirror, metal surface, window, especially the surface of plane mirror and concave mirror.

**Harmful Distance** is the maximum distance from the starting point of the laser beams to where people are right safe. The built-in harmful idstance of the Class 3R/III a laser is 1000m(3300ft) and the laser intensity will reduce to that of Class 1 products (which does not harm eyes) if people is out of this range.

### **CONTENTS**

1.	Nar	me and f	unction of eachpart	10
	1.	Name	10	
	2.	Keys Fu	nctions and information display	12
2.	Pre	paration	before measurement	13
	1.	Unpack	and store instrument	13
	2.	Setting	up the instrument	13
	3.	About t	he battery	15
	4.	Reflecti	ing prism	16
	5.	Load or	unload the base	16
	6.	Adjust 1	telescope objective and aiming target	16
	7.	Input N	1ode	16
		7.1	Input characters	
		7.2	Delete characters	18
	8.	Point Se	earch	19
		8.1	Direct search	19
		8.2	Wildcard search	
3.	Q-S	urvey		23
	1.		n the distance measurement	
	2.	EDM Se	etting	25
		2.1	Set the mode of EDM	25
		2.2	Atomosphere setting	27
		2.3	Grid factor setting	30
		2.4	EDM signal	32
	3.	Start m	easurement	33
		3.1	Set HA	33
		3.2	Set Station and instrument height	36
		3.3	Measurement	37
		3.4	Code	38
4.	Fur	ntions		40
	1.	Level		40
	2.	Offset		41
		2.1	Distance Offset	41
		2.2	Cylinder Offset	42
		2.3	Angel Offset	44


	3.	NP/P To	oggle	46
	4.	Height	Transfer	46
	5.	Hidder	n Point	50
	6.	Free Co	oding	52
	7.	Laser P	Pointer	52
	8.	Light		52
	9.	Unit Se	etting	53
	10	. Ma	ain Setting	53
	11	. ED	DM Tracking	54
5.	App	olication	ns	55
	1.	Setting	g the Job	55
		1.1	Create a new Job	55
		1.2	Select anExisting Job from Memory	57
	2.	Setting	g the Station	58
		2.1	Select the coordinate from memory [Find]	59
		2.2	Select the Fix Point in the Memory [List]	61
		2.3	Input the coordinates manually	62
	3.	Setting	g the Orientation	63
		3.1	Manual input orientation	63
		3.2	Set orientation with coordinates	65
	4.	Startin	g the Applications	66
	5.	Survey	ring	67
		5.1	Individual Point	70
		5.2	Data	71
	6.	Stakeo	ut	73
		6.1	Set Stakeout Point	73
		6.2	Polar Stakeout Mode	77
		6.3	Orthogonal to StationStakeout Mode	80
		6.4	Cartesian Stakeout Mode	83
		6.5	[Polar]	86
	7.	Resect	ion	89
	8.	Tie Dis	tance	93
		8.1	Polygonal	93
		8.2	Radial	96
	9.	Area		99
	10	. Re	emote Height	102
		10.1	Prism High Unknown	104
	11	. CC	0GO	105
		11.1	Traverse	106

		11.2	Inverse	110
		11.3	Bearing-Bearing Intersection	113
		11.4	Bearing-Distance Intersection	115
		11.5	Distance-Distance Intersection	118
		11.6	Line-Line Intersection	121
		11.7	Distance-Offset	123
		11.8	Set Point	125
		11.9	Extension	127
	12	. Ro	ad	130
		12.1	Road Manage	130
		12.2	Horizontal curve definition	131
		12.3	Vertical curve definition	138
		12.4	Road Stakeout	140
	13	. Sta	keout Reference Element	144
		13.1	RefLine	144
		13.2	RefArc	152
6.	File	manage	2	162
	1.	Job		162
		1.1	Select a Job	162
		1.2	New a Job	163
		1.3	Delete a job	165
	2.	Fix Pt		166
		2.1	Search Fix Pt	167
		2.2	Add Fix Pt	168
		2.3	Edit Fix Pt	169
		2.4	Delete Fix Pt	170
	3.	Meas. I	Pt	171
		3.1	View the measurement data	171
		3.2	Delete measurement data	172
	4.	Code		173
		4.1	Input Code	173
		4.2	View Code	175
		4.3	Delete Code	176
	5.	Memor	ry Statistics	178
7.	Data Transfer		179	
	1.	Data In	nport	179
	2.	Data Ex	cport	181
8.	Inst	rument	Setting	184
	1.	Genera	ll Setting	184

	2.	EDM Se	tting	188	
9.	Adj	ust and T	ools	189	
	1.	Adjust		189	
		1.1	View adjust parameters	189	
		1.2	Adjust Index Error	190	
		1.3	Adjust Tilt X	190	
		1.4	Adjust Tilt Y	192	
		1.5	Instrument constant setting	194	
		1.6	Factory setting	194	
	2.	System	infomation	195	
		2.1	View System Information	195	
		2.2	Set System Date	195	
		2.3	Set System Time	195	
		2.4	Firmware Upgrade	196	
	3.	Checkou	ut and calibration	200	
		3.1	Tube level	200	
		3.2	Circular level	200	
		3.3	Telescope reticle	201	
		3.4	The verticality of collimation axis and horizontal axis(2C)	202	
		3.5	Vertical plate index zero automatic compensation	203	
		3.6	Vertical collimation error (I Angle) and vertical collimation	zero	
		value s	etting	203	
		3.7	Plummet	204	
		3.8	Instrument additive constant (K)	206	
		3.9	The parallelism of collimation axis and photoelectricity axis	206	
		3.10	No prism ranging	207	
10.		Technica	al parameters	208	
11.		Attachm	nent A Road calculation example	210	
12		Attachment B File format introduction 215			

# 1. Name and function of eachpart

# 1. Name





# 2. Keys Functions and information display



Кеу	Function
0	Power ON/ Power OFF.
MEAS	Trigger key, depends on setting, maybe disting& save,
	disting or none.
ESC	Cancel or exit.
ENT	Confirm or commit editing.
	Switch pages
FNC	Hot key to enter function menu in measuring interface.
<b>A</b> 1	User defined function key 1.
A2	User defined function key 2
<b>A</b>	Move cursor up or goto previous.
▼	Move cursor down or goto next.
◀	Move cursor left or goto left.
<b>&gt;</b>	Move cursor right or goto right.
STU GHI	Entering letters A-Z.
1 ~ 9	
0~9	Entering number or choose menu item.
F1 ~ F4	Soft keys to choose screen bottom function.

# 2. Preparation before measurement

### 1. Unpack and store instrument

### Unpack

Put down the box gently and turn up the cover then turn on the lock, open the cover and take out the instrument.

### Deposit

Cover up the telescope mirror and make the vertical motion of alidade upwards then put the instrument horizontally (keep the objective upwards) into box. Then screw vertical motion gently. Cover up the box cover andlock the box. Loose horizontal and vertical axis as much as possible to reduce he shock damage to instrument.


## 2. Setting up the instrument

If the battery is mounted after the instrument is set up, the instrument will tilt slightly. So, first mount the battery, then set the instrument up.


### Operating reference

### 1. Centering and levelling

- 1) Setting up the tripod
  - (1) Extend the tripod legs toprovide a comfortable posture.
  - ②Setting up the tripod over the marked point on the ground, and center it.
- 2) Install the instrument on a tripod
  - 1) Place the instrument on the tripod head.
  - ②Fix the instrument on the tripod.
- 3) Leveling instrument roughly by circular level
- ①Turn on the instrument and switch the laser plummet and the electronic level function on.
- ②Move the tripod legs and use the tirbrach screws to center the instrument over the ground point. Adjust the tripod legs to level the circular level.
- 4) Leveling instrument accurately by tubelevel
- ①Loosen the horizontal clamp, and turn the instrument until the plate level is parallel to the line between leveling foot screws A and B. Use leveling foot screws A and B to center the bubble.



②Rotate instrument 90°by vertical axis, then use foot screw C to center the bubble.



③Repeatsteps above until the bubble is at the same place in all directions.

### 2. Centering by centering tool (optional or laser)

### 1) Set up a tripod

Extend a tripod to the appropriate height make sure the legs are spaced at equal intervals and the head is approximately level .Set the tripod so that the head is positioned over the surveying point. Brace tripod on the ground and keep one leg fixed.

### 2) Set up instrument and spotting

Put instruments on a tripod carefully, and tighten the center connection screw. Adjust the optical centering tool to make reticule clear (open instrument and laser centering if it's a laser centering tool). Handle another two unfixed legs, and adjust their position through the observation of the optical plummet. Make the three legs of the tripod fixed on the ground when the optical plummet is aligned to the station approximately . Adjust three feet screws of total station and keep the optical centering tool (or laser centering) aiming at the station accurately.

3) Leveling instrument roughly by circular level

(Same as The section above that discusses centering and leveling with plumb bob)

4) Leveling instrument accurately by tubelevel

(Same as The section abovethat discusses centering and leveling with plumb bob)

5) Centering and leveling accurately

Loosen center connection screw slightly and move instrument horizontally(Don't rotate instrument) through observation to optical plummet, making the

instrument aim at station accurately. Tighten the center connection screw and leveling instrument accurately again.

This operation should be repeated till the plumb aims at station accurately.

# 3. About the battery

### Mounting the battery

- ☆ Fully charge the battery before measurement.
- $\stackrel{\star}{\sim}$  Cut off the power before removing the battery.
- ► Step mounting the battery
- 1. Insert the battery to the instrument.
- 2. Press the top of the battery until you hear a click sound.
  - ► Step Remove battery
- 1. Press the button downward.
- 2. Remove the battery by pulling it toward you.
- Battery information
  - ——Power is adequate, operating available.
  - The battery can be used for 4 hours when this symbol first appears. If you cannot master the consumed time, you should prepare a spare battery or charge the battery before using.
  - ☐ ——End of the operation as soon as possible and replace the battery and charge if running out of power.
  - ①——It takes several minutes for the instrument to shut down when this symbol first appears. The battery has few power now and should be replaced an recharged.

### **Notice:**

- 1 The operating time of battery depends on environmental conditions such as ambient temperature, time and times of charging and so on the battery is suggested to be prepared or charged ahead before operation to keep it safety.
- 2 The battery symbol only indicates power capability undercurrent measurement mode. The remained capacity of the battery shown under current mode does not guarantee its capacity under other modes .Because consumption of power in distance measurement mode is more than that in angle measurement mode ,the instrument may end ranging sometimes due to insufficient capacity of battery (when switching between modes).

### **Notice in charging:**

- Though overcharging protection is installed in the instrument, please plug off the battery immediately after finishing charging.
- Charging range from 0°~±45°C. Abnormal responds of instrument occurs over this range.
- Rechargeable for300—500 times, it may shorten Service time of the battery

completely.

• Charge the battery once a month no matter if it is used to prolong its longevity.

### 4. Reflecting prism

When using a prism mode for measuring distance, reflection prism should be placed where the target is. A reflecting prism group includes one or three prisms that can connect prism group placed at the base of the tripod with the dock connector or by placing them in the stem directly. Prism group may need to be configured by users based on target.

### 5. Load or unload the base

#### Load

Put the three fixed feet in the corresponding bases, make the instrument in a triangular base, clockwise lock the button by  $180^{\circ}$  to lock the base, and then fix screw with a screwdriver to screw it out at a fixed lock knob.

### Unload

If necessary, the triangle base can be removed from the instrument (including the same base of reflection prism base connector) by loosening the lock knob base fixed screw with a screwdriver, and anticlockwise locking button about  $180\,^\circ$ , then separate the instrument from base.

# 6. Adjust telescope objective and aiming target

Aiming method (reference)

- ① Rotate the telescope and point it to the bright sky and focus reticule clearly (by rotating eyepiece in own direction and focusing reticule slowly).
- ② Aim at the target with the crosswire in optical sight, and keep an appropriate distance when aiming (about 200mm).
  - ③ Use telescope focus screw to make target clear.

It means that focus or eyepiece diopter is not adjusted adjusted when there is a parallax with eye moving up and down, thus focus carefully and adjust eyepiece to reduce parallax.

# 7. Input Mode

Total station keybord includes alpha/digit keys. User can input letters and numbers directly.

### Input box:

Each digit key defines 3 letters and 1 number. Depends on the properties of input box, input process varies.

### Number input box:

In number input box, user can only input numbers, include "1-9",".", "-+". Number will appear in box when user presses the key.

### Text input box:

In text input box, user can input numbers and letters. Repeat pressing same key to get proper letter, such as A->B->C->7.

When right-bottom of screen display icon AB, user can input number/letter; when display icon 01, user can only input number. User canpress soft-key [F4] to switch input mode between Number and Text when input box beenactive.

### • Letters:

Letters that total station can input includes "A-Z/\$%\_@&\*?!+-.".

- ➤ Arrow key move inputing cursor.
- PressingENT entersediting; pressingENT confirms input after editing.
- When editing distance, angle, temperature and pressure values that containunit format, input box's text will convert into text without unit format. Such as angle 29° 32′ 56″ transforms into 29.3256; Distance 115.321m transforms into 115.321. When finish editing, the text will automatic convert back.


### 7.1 Input characters

Each digit key defines 3 letters and 1 number. In text input mode, each time pressing the key, one character appears at cursor position. Number appears when pressing 4 times.

Example: input 123ABV2

Steps	Key	Display			
1 Pressing key to start inputing. Right-bottom screen displaying icon 12 means in number input mode.		Pt. T. H. Code HA VA B.S.	[Q-Surv : : : : : Clear	ey] 1/3  1	

**Total Station Manual** 




### 7.2 Delete characters

Delete or clear input characters.

Delete of clear input characters.					
Steps	Key		Di	splay	
① Press key — to move cursor to right side of the character that to be deleted.	←	Pt. T. H. Code HA VA B.S.	[Q-Surv : : : : : Clear	PTT   001	

**Total Station Manual** 



### 8. Point Search

Point search is a function used by applications to find measured or fixed points in the jobs.  $\circ$ 

Point search is limited to a particular job.


If several points meet the search criteria, then the results are ordered according to the date.

### 8.1 Direct search

By entering an actual point number (for example 'A1'), and pressing key SEARCH, all points within the selected job and with the corresponding point number are found.


Here is an example for searching fix point in function 'Set STA'.

Steps	Key	Display
① Choosing 'Survey' in application menu, then choose function 'Set STA'. Entering point number, for example 'A1', pressing ENT to finish input, then pressing F1 to search.	[F1]	[Set STA] Input STA PT! Station: A1  Find List Coord.





Soft keys introduction:

[View] Show the coordinate of selected point.



[Coord.] Input point manually.






Job

Zero Coord.

Find

Total Station Manual



[OK] Commit selected point.

### 8.2 Wildcard search

The wildcard search is indicated by a "\*". The asterisk is a place holder for any following sequence of characters. Wildcards should be used if the point number is not fully known, or to search for a batch of points.

### Examples:

- \* All points are found.
- A All points with exactly the point number "A" are found.
- A\* All points containing "A" are found, for example, A1, A2, 1A.

Steps: (For example "\*")

Steps	Key	Display
(1) Choosing 'Survey' in application menu, then choose function 'Set STA'. Entering "*", pressing ENT to finish input, then pressing F1 to search.	[F1]	[Set STA] Input STA PT! Station: *  Find List Coord.
② In searching result		[Find Pt.] 1/5
window, using arrow key 1	$\uparrow$	A1 Station A2 Station A3 Meas. PT
to move cursor to select	[F4] [ENT]	B4 Meas. PT CO Fix Pt.
point number. Press key F4 or		View Coord. Job OK
ENT to conirm selecting.		


# 3. Q-Survey

### 1. Notes in the distance measurement

After the placement of instrumentand turned on the power, total station is ready, can start measuring.

In measurement display, user can call the function of set key, the functionkeys and hotkey.

The show is an example. Localized version may be slightly different. The example of Q-Survey show:



F1-F4 Start the corresponding functions

### **Notes:**

Measurements to strongly reflecting targets such as to traffic lights in Reflector EDM mode without prism should be avoided. The measured distances may be wrong or inaccurate.

When a distance measurement is triggered, the EDM measures to the object which is in the beam path at that moment.

If e.g. people, cars, animals, swaying branches, etc. cross the laser beam while a measurement is being taken, a fraction of the laser beam is reflected and may lead to incorrect distance values.

Avoid interrupting the measuring beam while taking reflectorless measurements or measurements using reflective foils.

- No Prism Ranging
- Ensure that laster beam is not feflected by any object with high reflectivity and

- close to the light path.
- When start the distance measurement, EDM will measure distance for the object in the light path. If there are temporary obstacles in the light path (such as by car, or the heavy rain, snow, or filled with fog), the distance measured by EDM is the distance to the nearest obstacle.
- When a long distance measurement, laser beam deviation of collimation line will affect the accuracy of measurement. This is because the divergence of the laser beam reflection point may not be with the crosshair sighting points coincide. It is recommended that the user accurately adjust to ensure that is consistent with laser beam collimation. (Please refer to "20.10 NO Prism Ranging" in the Chapter 9)
- Don't use two instruments to measure the same target at the same time .
- Red light cooperates with reflective pieces to measure distance

  Laster can also be used to measure distance for eflectivepieces. To guarantee the accuracy of measurement, the laser beam is perpendicular to the reflector plate, and through accurate adjustment. (Please refer to "3.10 NO Prism Ranging" in the Chapter 9)

Ensure proper additive constant of different reflection prism.

# 2. EDM Setting

### 2.1 Set the mode of EDM


Select the mode of distance measurement, there are 6 modes : Single, Repeat, Tracking, 3 Times, 4 Times, 5 Times.

Steps	Key	Display
① Press [F4]( ↓ )and show the second soft key in the Q-Surveying. Press [F3] to enter the interface of EDM Setting.	[F4] [F3]	[Q-Survey] 1/3  Pt. : 1
② When the cursor is in EDM mode option,Press the direction key of → to select the mode of measurement.Each time you press ←or→, the mode of measurement is switched.		[EDM Setting]  EDM Mode: Single () Reflector: Non-Prism () P.C. : 0 mm
③ After finishing setting, press [F3](OK) to return the function of Q-Surveying.If you want to cancel the settings, press [ESC] to ignore the changes.	[F3]	Setting Saved!

### Set the reflector type

Our series total station can be set up for the red laser (RL) range and invisible infrared light (IR) range and the total station has three reflectors to be selected, which are prism, non-prism (NP) and reflect board (Sheet). You can set by job, but the prism used should be matched with prism constants.


# ➤ About the parameters of various reflectors in distance measurement, please refer to "Technical Parameters".



### Set up the Reflecting Prism Constant.

As a prism is selected as a reflector, a prism constant should be set before any measurement. If the constant is entered and set, it is saved and will not be erased after switching off the instrument.

Example: Prism Constant is -30mm



- <sup>№1</sup>: Prism constant you enter is effective only when the reflector mode isPrism.
- $\%^2$ : The range of Prism constant value: -99mm $\sim$ +99mm.
- ¾³: Range mark: In the bottom right corner of the page as shown above, this mark is the distance Range identifier, where R4 represents 400m, L6 stands for 600m, and so on. That is the maximum distance from the prism-free mode range in good weather conditions (visibility is not less than 30km).

### 2.2 Atomosphere setting

### Refraction:

When measuring horizontal distance and elevation, our instrument corrects the atmospheric refraction and the earth curvature automatically.

The instrument supports of atmospheric refraction coefficient have three option, they are 0.00, 0.14, and 0.20.

Note: The refraction of instrument has been set for K=0.00 when left factory .It also

### can be set to other values

Steps	Key	Display
① After entering to the interface of EDM Setting, press [F1] (Atoms) to enter the interface of Atomspheric Data.	[F1]	[EDM Setting]  EDM Mode: Single Reflector: Prism 1 P. C. : 30.0 mm
② Interface displays the current setting, using the direction of ↓ to move the cursor to the setting item of Refraction.  Press ←→to select the value of refraction.Each time you press ← or →, the value of refraction is switched.	+	[Atomspheric Data]  Temp. : 20.0 °C  Press : 1013 hPa  PPM : 0.0 PPM  Refraction 0.00 (1)
③ After finished setting, press [F4] (OK) to save settins and back to previous menu.  If you want to cancel the settings,press [ESC] to ignore the changes	[F4]	[EDM Setting]  EDM Mode: Single () Reflector: Prism () P.C. : 30.0 mm

### **Atmospheric Correction:**

When measuring distance, the measured value will be influenced by the atmosphere.

In order to reduce the influence, a atmospheric correction parameter is needed. Correction value associated with the pressure and temperature in air.Calculated

### as follows:


If the air pressure unit is mmHg, Make a conversion according to the formula:  $1hPa=0.75mm\ Hg$ 

> Standard meteorological conditions (atmospheric correction value =0 ):

press: 1013hPa temperature: 20℃

> If the atmospheric correction is not required, please set PPM to zero.

If the atmospheric correction is not required, please set PPM to zero.				
Steps	Key	Display		
① After entering to the interface of EDM Setting. Press [F1] (Atoms) to enter the interface of Atomspheric Data.	[F1]	[EDM Setting]  EDM Mode: Single Reflector: Prism Prism And Strong Prism An		
② Interface displays the current settings.	<b>↓</b>	[Atomspheric Data]  Temp. : 20 °C  Press : 1013 hPa  PPM : 5.6 PPM  Refraction 0.00		
③ Input the value of temperature. example: Enter 26 °C and press the key of [ENT]. The cursor moves to the setting item of Press.	[ENT]	[Atomspheric Data]  Temp. : 26 °C  Press : 1013 hPa  PPM : 5.6 PPM  Refraction 0.00		
(4) Input the value of atmospheric pressure. example: Enter 1020 hPa and press the key of[ENT]. Program calculates the value of PPM and the cursor moves to the	[ENT]	[Atomspheric Data]  Temp. : 26 °C  Press : 1020 hPa  PPM : 3.7 PPM  Refraction 0.00		



- %1: The range of enter: Temp.(-30  $^{\circ}$ C $\sim$ 60  $^{\circ}$ C), Press.(500hPa $\sim$ 1400hPa).
- ※2: The instrument calculates the value of PPM according to the values of temperature and pressure you enter.
- ※3: Press [F1](PPM=0) can set the value of PPM to 0.
- X4: If instrument supports temperature pressure sensor, you can press [F2] to receive the values of air pressure, temperature and calculate the correction valueautomatically.

### 2.3 Grid factor setting

When calculating the coordinates, the horizontal distance measured must multiply by the scale factor.

### **Computation formula**

1.Altitude factor=R/(R+ELEV)

R: The average radius of earth

ELEV: mean sea level altitude

2.Scale factor

Scale factor: Scale factor of the station

3.Grid factor

Grid factor=altitude factor×scale factor

### **Distance calculation**

1. Grid distance

HDg=HD×grid factor HDg: Grid distance

HD: Ground distance

2. Ground distance

HD=HDg/(Grid factor)

### Note:

- 1. The enter range of the scale factor: 0.99~1.01, the default value is 1.0.
- 2. The enter range of the average height above sea level: -9999.9999~9999.9999. The average altitude retained after the decimal point one, the default value is 0.

Steps	Key	Display
① After entering to the interface of EDM Setting,press the key of [F4] to enter the second page of soft key, then press te key of [F1](Grid) to set the Grid Scale.	[F4] [F1]	[EDM Setting]  EDM Mode: Single () Reflector: Prism () P. C. : 30.0 mm
2 Interface displays the current setting.Enter the values of Scale and Altitude then press the key of [ENT].Program calculates the Grid Scale and displays it in the interface.If you want to set all enter area to 0,you can set the key of [F1] (Reset).	[ENT]	[Grid Scale]  Scale : 1.0000 Altitude: 0.000 m  Grid Scale 1.0000  Reset OK
3 After finished setting, press [F4](OK) to save settins and back to previous menu. Then press the key of [F3](OK) to save the setting of EDM and back to the function of measurement.	[F4]	[EDM Setting]  EDM Mode: Single () Reflector: Prism () P. C. : 30.0 mm

# 2.4 EDM signal


The function of signal is to display the intensity of signal received by total station. If the target is hard to be found or can't see, using the function can achieve the best sighting accuracy.


Steps	Key	Display
① After entering to the interface of EDM Setting,press the key of [F4] to enter the second page of soft key, then press te key of [F2](Signal) to enter the function of Signal intensity.	[F4] + [F2]	[EDM Setting]  EDM Mode: Single Prism Prism Single Prism Signal F-
② Using the bar chart and value of number to show the intensity of signal received by total station in the screen. As shown in the picture on the right.		[EDM Signal] Strength: 50
③ Press [F1] or [ESC] to back to the menu of EDM setting.	[F1] or [ESC]	[EDM Setting]  EDM Mode: Single   Reflector: Prism   Prism   30.0 mm


### 3. Start measurement

Q-Survey has 3 pages menu, including all measuring functions commonly used, such as angle measurement, distance measurement and coordinate measurement. As shown

### below:









### 3.1 Set HA

You can set the horizontal angle as 0 or set it as wanted angle.


### Set horizontal angle to 0.




**Total Station Manual** 



### Set HA.





# 3.2 Set Station and instrument height

After set the coordinate of station (the site of instrument) relatives to the origin, the instrument can calculate the coordinate of the location to your position (the site of prism).

You can set station and the instrument height conveniently in the Q-Survey.

Steps	Key	Display
① Aim at the target which used to orient.Press [F4] twice to enter third pages soft key.	[F4] + [F4] + [F2]	[Q-Survey] 1/3 Pt. : A1 □ T. H. : 1.500 m Code : 1 HA : 13° 29′ 59″ VA : 90° 59′ 23″  ■ : ALL DIST REC ↓  ALL Code EDM ↓ Station Zero SetHA ├─
2 Press [F1] (Station) to enter the interface of Enter STA. Enter the name of station, the instrument height and coordinates. After entering each item, move the cursor to the next edit text.	[F1]	[Input STA]  Station  IH.
(3) After finished entering, press [F4] (OK) to save the data of station and back to the function of Q-Survey.	[F4]	[Q-Survey]       1/3         Pt.       :         T. H.       :         Code       :         HA       :         VA       :         90°       59′         23″         :         Station       Zero             1         A1       M         1       1         20°       00′         30°       00′         23″       0         30°       00′         30°       00′         30°       00′         30°       00′         30°       00′         30°       00′         30°       00′         30°       00′         30°       00′         30°       00′         30°       00′         30°       00′         30°       00′         30°       00′         40°       00′         50°       00′         60°       00′         70°       00′         80°       00′         80°       00′

## 3.3 Measurement

After all settings have been finished, you can start to measure. There are 3 pages to display the result of measurement, including all measurement data and you can press [PAGE] to view.


Steps	Key	Display
① Input the name of point and instrument height. Move the cursor to the next edit text after entering each item. You can enter Code when necessary.	[ENT] + [ENT]	[Q-Survey] 1/3  Pt. : A1  T.H. : 1.500 m (1)  Code : 1  HA : 0° 00′ 00″  VA : 90° 59′ 23″  :  ALL DIST REC
② Aim at the center of prism, press [F1](ALL) or [F2](DIST)+[F3](REC) to start to measure and record the measurement data. The measurement data including angle data, distance data and coordinatedata.You can press [PAGE] to view.	[F1] or [F2] + [F3]	[Q-Survey] 1/3 Pt. : A1 T.H. : 1.500 m (1) Code : 1 HA : 0°00′00″ VA : 90°59′23″  : 10.011 m  ALL DIST REC
3 After finishing measuring a point, program makes the number of point add 1 automatically, aim at the center of prism and repeat the above steps to start next point measurement.		[Q-Survey] 1/3  Pt. : A2  T. H. : 1.500 m  Code : 1  HA : 0° 00′ 00″  VA : 90° 59′ 23″  : 10.011 m  ALL DIST REC

#### 3.4 Code

The code contains the information about the recording points, in the process of post-processing, with the help of encoding function , you can process conveniently according to the specific group. The function of "File Manager" also contains the information of code.

### **Simple Oeration of Code**

- 1. Move the cursor to the line of Code.
- 2. Enter the name of Code.
- 3. Press the key of [ALL] to start the distance measurement and record the data of code and measurement at the same time. If the name of code already exists in the code library, it will extract the information of code in the code library to record at the same time.



<sup>№</sup> :The order to save code and measurement data is set in the "Setting" function.


The set items of code record are Before REC and After REC.

Before REC: Record code data before recording the actual measurement data.

After REC: Record code data following after the actual measurement data.

#### Soft key of Code

After starting the function of soft key (Code), Screen displays the following:



GSI-the introduction of code properties:

Code: The name of code
Note: The additional note

Info1: The editable information of other contents

Info8: Other information

The introduction of soft key:

[Find]: Use the name of code or wildcard to find the needed code.

[New]: New a piece of editable information of code and use it.

[REC]: Record the current code data to the job and the code data not with any measurement point binding at this time.


[OK]: Select the current code and use it.

Using the soft key of [Code] can select the code in the code library directly, it will back to the interface of Q-survey after selecting, the code in the edit text of Code is the selected code.

### 4. Funtions

Bring the total station's common functions and settings together, they can be used in the process of measurement conveniently. In the function of Q-Survey which in the Main menu or other interface of measuremen in the program, you can press [FNC] to enter the menu of Function


The menu of Function has 4 pages, you can press 【PAGE】 to view. The specific introduction as follows:



You can open Function menu to select the function you want to use, you can also define the function which on the Function menu to the key of [USER1] or [USER2], then press the key of [USER1] or [USER2] to use these functions.

#### 1. Level

When the compensator is on, Compensator can compensate to the tilt caused by the instrument is not level. Manually level the instrument with the tribrach screws to make the compensation value of compensator tend to 0, by doing these can make the instrument tend to level. When the instrument is level, the laser plummet is in the direction vertical, the place of laser points is the place of instrument




- Press [On] to open the compensator and press [Off] to close the compensator.
- ◆ Press [X Only] to open the compensator of X direction.
- ◆ Press [▲][▼] to adjust the laser plummet brightness.
- ◆ Press [OK] to closs the laser plummet and exit.

### 2. Offset

The Offset is used to measure the points which are not intervisible or intervisible but can not set up prism in the Station.

Offset contains Dist.Offset and two subprograms, the two subprograms are Cylinder Offset and Angle Offset.


#### 2.1 Distance Offset



Using the external tools to measure the Offset values of the target point p2 and measurement point p1 along the line of station point and measurement point, the Offset values are Trav.OFS, LengthOFS and HeighOFS. Combining the information of measuring point (p1) can calculate the distance of station point (p0) to target point (p2), can also calculate the angel and coordinate.

When the measurement point is set on the left of target point or the right of target point, you should make the angle that between line of measurement point and target point and the line of measurement and station point about equals  $90^{\circ}$ . When the offset point is set on the front of target point or on the back of target point, you should make it on the line of station point and target point.

Steps	Key	Display
-------	-----	---------




**※**¹:

Rec/Reset: Make sure the inputed values of Offset and reset all the values of Offset to 0 after once measurement.

Permanent: The values of Offset are always working in the calculation of measurement point.


## 2.2 Cylinder Offset




As for the not intervisible cylinders, you can measure the angles of station point with cylinder in Hz Left and Hz Right and the shortest distance of station point to cylinder firstly. Then calculate the coordinate of cylinder center and radius of cylinder through the geometric relationships. The shortest distance between station point and cylinder is in the bisector of angle of station point with cylinder in Hz Left and Hz Right. Turning the instrument to make the collimation axis in the bisector of

angle that station point with cylinder in Hz Left and Hz Right, thus can measure the distance between cylinder and station.

Steps	Key	Display
① In the program of Q-Survey, press [FNC] to enter the menu of Function, then pressing [F2] to enter the program of Offset.	[F2]	[Function]       1/3         F1 Level       (1)         F2 Offset       (2)         F3 NP/P       (3)         F4 HT. Transfer       (4)         F1       F2       F3       F4
② Press [F2] to enter the subprogram of Cylinder Offset.	[F2]	[Dist. Offset] Input offset data! Trav. OFS: LengthOFS: HeightOFS: Mode: Reset Cylinder Angle OK
3 Aim at the left edge of cylinder, press [F1] to make sure the angel of Hz Left, turn the instrument to aim at the right edge of cylinder and press [F2] to make sure the angle of Hz Right.	[F1]+[F2]	[Cylinder Offset]         Hz Left : 125° 36' 25″         Hz Right : 88° 45' 46″         ∴ 0.000 m 1         △Hz : 1° 45' 46″         Prism OFS: 0.000 m         Hz Left Hz Right ALL         DIST REC EDM
④ Turn the instrument to make △ Hz=0, if use the prism, please input the thickness of prism in the edit text of PrismOFS, if don't use the prism, the default value is 0 in the edit of PrismOFS, then press [F3] to measure the shortest distance of the instrument to cylinder and enter the interface of	[F3] or [F4] + [F1]+[F2]	[Cylinder Offset]         Hz Left : 125° 36' 25″         Hz Right : 88° 45' 46″         ∴ 12. 124 m 1         △Hz : 0° 0' 0″         Prism OFS: 0.000 m         Hz Left Hz Right ALL         DIST REC EDM




## 2.3 Angel Offset



Angle Offset is used to measure the points which are intervisible but hava no reflector and can't set up the prism. The basic principle is making the target point and measurement point in the concentric circles whose center is station point, then measuren the position information of station point and measurement point and the angle offset of station to target point, thus can calculate the coordinate of target point.


Set the measurement point P in the place where is as far as possible to close the left or right of target point C, and make the distance between measurement point P and station point A and the distance between station point A and target point C are approximately equal.

Steps	Key	Display
① In the program of Q-Survey, press [FNC] to enter the menu of Function, then pressing [F2] to enter the program of Offset.	[F2]	[Function]       1/3       ▼         F1 Level       (1)         F2 Offset       (2)         F3 NP/P       (3)         F4 HT. Transfer       (4)         F1       F2       F3         F4       F4



# 3. NP/P Toggle

Switch the mode of reflector quickly. (P is the mode of Prism and NP is the mode of Non-Prism)




Open the first page of Function Menu and press [F3] to switch the mode of reflector.

# 4. Height Transfer


The functions of HT. Transfer as follows: Using the measurement data of target point, the fixpoints, fix measurement points and so on to calculate the height of current station point and set the height of station again. You can receive the coordinate of target point by calling the points in the file or through the keyboard to input, you can observe 5 fixpoints' height at most and to calculate.


The principle of Height Transfer:




PO Station point

P1~P3 Target fixpoints height









## 5. Hidden Point


The function of Hidden Point is using a specia hidden point measuring rod to measure the points which are not intervisible.



The length of measuring rod is known, by measuring the position information of prism 1 and prism 2 in the measuring rod and using mathematical methods to calculate the coordinate of hidden point on the other side of the measuring rod.

Steps	Key	Display
① In the program of Q-Survey, press [FNC] to enter the menu of Function, then pressing [PAGE] to open the second page of Function and then pressing [F1] to enter the function of hidden point measurement.	[F1]	[Function] 2/3 ← F1 Hidden Point (5) F2 Free Coding (6) F3 Laser (7) F4 Light (8) F1 F2 F3 F4
② In the interface of measuring the first prism point, pressing [F4] to enter the interface of Rod Length.	[F4]	[Hidden Point]  Meas. target 1!  Pt. : 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1






# 6. Free Coding

Please refer to "3. Q-Survey" → "3. Start Measurement" → "3.4 Code"


## 7. Laser Pointer

Open or close the laser fastly.



# 8. Light


Turn on or off the light of instrument screen fastly.



Open the second page of Function Menu and press [F4] to turn on or off the Light.

# 9. Unit Setting


Set the common Unit fastly.



Open the third page of Function Menu and press [F1] to enter the interface of unit setting. After finishing setting the units in the interface of Unit Setting, press [F4](OK) to save the settings, press [F1](Reset) to restore all units to factory default.

## 10. Main Setting


Open the settings about instrument's hardware, the specific items as follows:



As for the setting of specific items, please refer to "General Setting".

# 11. EDM Tracking

Open or close the mode of EDM Tracking fastly.




Open the thied page of Function Menu, press [F3] to open or close the mode of EDM tracking.

# 5. Applications

Prepare setting before measuring:

Before startingthe application, there are some preparations needed to set up. The Pre-Settingsscreenwill beshown after the user selects an application. User can select and set the content of the Pre-Settings menu successively.



- [\*]: Setting has been done.
- [ ]: Setting has not been done.

The details of every setting are as follows.


## 1. Setting the Job

The measured data and fix data are saved in the jobs which are shown as childdirectories. The job contains different types of data, such as fix points, measured points, station points, codes, etc. The datas in the job can be read, edited and deleted.

#### 1.1 Create a new Job

Steps	Key	Display	
① Press [F1] in the Pre-Settings screen. Then enter the Set Job function.	[F1]	[Surveying]  [*] F1 Set Job  [ ] F2 Set STA  [ ] F3 Set B.S.  F4 Start  F1 F2 F3	(1) (2) (3) (4)

② Press [F2](New) and then enter the Create a New Job screen.  Press [F4](OK), the displayed job will be set as current job and then back to Pre-Settings screen.	[F1]	[Set Job] Job : DEFAULT  Operator: Date : 20150515 Time : 14:10:20  List New OK
③ If the instrument is fitted with SDCard, there willfirstly showthe diskselection screen. In this screen, user can select the disk through Up or Down key. Then press [F4](OK) to confirm.  A: Local Disk  B: SD Card		[Select Disk]  A:Local Disk  B:SD Card  Prop. OK
4 Continue to show New Job screen. Input the new job's name, operator, etc. Press [ENT] to finish one input item and thecursor moves to the next input itemautomaticallyat the same time. $X$	Input job's data + [ENT]	[New Job]  Job : JOB1  Operator: Note1 : Note2 : date : 20150515 Time : 14:10:20  Back OK
S Press [F4](OK) to complete setting a new job after finishing all the inputs. This job will be set as the current job. Then back to the Pre-Settings screen.The completed setting item is marked with [*].	[F4]	Job Set!




X: The instrumentsystem will create and add date and time automatically.

# 1.2 Select an Existing Job from Memory

If there is any job existing in the memory, user can select this job and set it as the current job.

Steps	Key	Display
① Press [F1] in the Pre-Settings screen. Then enter the Set Job function.	[F1]	[Surveying]  [*] F1 Set Job (1)  [] F2 Set STA (2)  [] F3 Set B.S. (3)  F4 Start (4)  F1 F2 F3 F4
② Press [F1] (List) to enter Job list screen.	[F1]	[Set Job] Job : DEFAULT  Operator: Date : 20150515 Time : 14:10:20  List New OK
3 All the existing jobs, including that stored on SD Card and will be shown as a list. The current job is marked with a *. Select the target job through Up and Down key and then press [F4](OK) to confirm the selection. The selected job		[Job list]  JOB1  JOB2  JOB3  JOB4  [SD]  Delete New View OK




Note: Don't pull out the SDCard when it is in operating state, otherwise it will cause the SDCard'sdata loss or damage.

- All measureddatas are stored in the current job.
- ➤ If start the application without setting the job, press ALL key or press REC key in the Q-Surveying screen, the instrument system will create a job which named DEFAULT automatically.


# 2. Setting the Station

Every target coordinate's calculation is related to the position of the station. The station coordinate can be input manually or selected from the instrument memory.



### 2.1 Select the coordinate from memory [Find]

- 1. Select the coordinate from memory.
- 2. Input instrument height.
- 3、[OK] Set station.





name and press [F4](Find). If [Input Coord.] the point is found, press [OK] in DEFAULT Job Pt. 121 the [Find Pt.] list screen to set it N 0.000 m as station. Program enter input 0.000 m Ε 0.000 m Z instrument height screen. If the point doesn't exist, press **Back** OK [F3](Coord.) to input the coordinates of N, E and Z. Set this point as station. [Zero]: Set this point's all coordinates as 0 and set the point as station. [Coord.]: Enter [Input Coord.] screen. Input the coordinates and save them to the current job. (4) Enter input instrument Input [Set STA] height screen. Input the instru instrument height and press ment Input I.H! [ENT] to confirm. Then press height IH. 1.400 m [F4](OK) to save and set the station informations. [ENT] Press [ESC] then back to **Back** previous screen. Continue to set [F4] the coordinates of station. [Surveying] [\*] F1 Set Job (1) (5) Back to Pre-Settings screen. [\*] F2 Set STA (2) Set B.S. F3 (3)The setting items that have F4 Start (4) been made are marked with \*. F1 F2

 $X^1$ : The details of [Find Pt.] can be found in the chapter "Find Point". You can also input the wildcard "\*" to search all the points.

## 2.2 Select the Fix Point in the Memory [List]

User can select the fix point in the memory's jobs to set station without inputting the point name.






## 2.3 Input the coordinates manually.

- 1. Press [Coord.], enter input coordinate screen.
- 2. Input the point name and coordinates.
- 3. [OK] Save the station coordinates. And then input the instrument height.

Steps	Key	Display
② Press [F3](Coord.) in the [Set STA] screen.	[F3]	[Set STA] Input STA PT! Station: A1  Find List Coord.
③ Input the point name and the point's coordinates. After inputting one item, the curser will move to next input item.	Input point name and coordinate + [ENT]	[Input Coord.]  Job : DEFAULT  Pt. A1  N : 3.102 m  E : 15.012 m  Z : 4.215




# 3. Setting the Orientation

The orientation can be input manually or determined from points that are either measured orselected from the memory.

## 3.1 Manual input orientation

- 1. Press [F1] and enter manual input screen.
- 2. Input the azimuth, prism height and point name.
- 3. Press [F1](ALL) to start measuring and set theorientation.
- 4. Press [REC] to record theangle and orientation.


Steps	Key	Display
① Press [F3] in the Pre-Settings screen. Then enter the Set STA function.	[F3]	[Surveying]  [*] F1 Set Job (1)  [*] F2 Set STA (2)  [ ] F3 Set B.S. (3)  F4 Start (4)  F1 F2 F3 F4
② Press [F1] and select the [Angle Setting] to input orientation manually.	[F1]	[Set B. S.]  F1 Angle Setting (1) F2 Coordinates (2)
③ Aim B.S. point and then input the azimuth, prism height and backsight point name. Press [ENT] after finishing every input.	Input horizontal angle + [ENT]	[Angle Setting] Azimuth: 50 ° 00′ 00″ T.H.: 1.500 m  BS PT: DEFAULT1 Aim BS. Then ALL/REC!  ALL REC Zero EDM
4 Press [F1](ALL) to start measuring and set the orientation. [REC]: Press this key to finish setting orientation without measurement. [Zero]: Set the azimuth as 0.	[F1]	BS SET!




### 3.2 Set orientation with coordinates

The determination of the direction value can also be carried out using a point with a known coordinate.

- 1. Press [F2] to go to set orientation with coordinates
- 2. Input the name of orientation point and find the point.
- 3. Input the prism height and determine it.
- 4. Use this point to set orientation.
- The orientation point can be select from memory or inputted manually.





# 4. Starting the Applications

The preset applications covers a wide range of measurement tasks. That makes the daily field measurementeasier and faster. The all applications can be selected to use are as follows:

Surveying


- Stakeout
- Free Station
- Tie Distance
- Area
- Remote Height
- COGO
- Road

### Steps:

- 1. Go to the MAIN MENU.
- 2. Move the focus to [Program] or press the Numeric key 2 to select and go to the PROGRAM MENU.
- 3. Press [PAGE] to browse the application menu. Press [F1]-[F4] to select and start an application.


# 5. Surveying

Compared with the Q-Suveying, Surveying has different guides in setting station and set orientation.



Operation: Must first finish seting the station and orientation.

Steps	Key	Display
-------	-----	---------




## **5.1 Individual Point**

# [IndivPt]:

In the data acquisition, point can be recorded individually. Press this key to switch the screens of Individual Point Measurement and Consecutive Point Measurement.

Steps	Key	Display		
① Press [F4](↓) twice to display the last page of soft keys.	[F4]	[Surveying] 1/3 Pt. : 1 ☑ T. H. : 1.500 m Code : 1 HA : 13° 29′ 59″ VA : 90° 59′ 23″  ■ .  ALL DIST REC ↓  ALL IndivPt Data ←		
② Press [F2](IndivPt) to start measuring individual point function.	[F2]	[Surveying] 1/3 IndivPt: 2 T. H. : 1.500 m 1 Code : 1 HA : 13° 29′ 59″ VA : 90° 59′ 23″  ALL IndivPt Data		
③ Input the individual point's name and prism height and press [ENT] to move the cursor to next input item If needed, input the code.	Input point name, prism height and code + [ENT]	[Surveying] 1/3 IndivPt: SPI T. H.: 1.500 m Code: 1 HA: 13° 29′ 59″ VA: 90° 59′ 23″  ALL IndivPt Data		




#### 5.2 Data

## [Data]:

Look over the measured datas which are saved in current job.

Steps	Key	Display		
① Press [F4]( ↓ ) twice to display the last page of soft keys.	[F4]	Pt. : T. H. : Code : HA : VA : ALL DI	1.500 m 1 1.500	
② Press [F3](Data) to start view measured point function.	[F3]	IndivPt : T. H. : Code : HA : VA :	1.500 m 1 1.500 m 1 1.500 m 1 1.500 m 1 1.500 m 1 1.500 m 1	



### 6. Stakeout

The Stakeout Application can calculate lofting elementsbase on lofting point's coordinate or manually input angle or horizontal distance. The application can continuously display differences, between current position and desired stake out position.

### **Steps of Stakeout:**

- 1. Set the job.
- 2. Set the station
- 3. Set the orientation
- 4. Extractecoordinates from memory. The coordinates may be a measured point or a manually entered fix point.
- 5. Start staking out. There are three ways to choose: Polar Stakeout mode, Orthogonal to StationStakeout mode, Cartesian Stakeoutmode.

#### **6.1 Set Stakeout Point**

### Extractecoordinates from job

Steps	Key	Display
① After finishing setting the job, setting the station and setting the orientation, press [F4] to startstaking out in the Pre-Setting menu. ※¹	[F4]	[Stakeout]  [*] F1 Set Job (1)  [*] F2 Set STA (2)  [*] F3 Set B.S. (3)  F4 Start (4)  F1 F2 F3 F4
② Input the name of stakeout point in the Search item. Press [ENT] to start Find Point function. (Or input wildcard "*"to start the wildcard search.)	Inputstakeout point's name + [ENT]	[Stakeout] 1/3

(3)


#### A:


The program searchs the point name in the job and show the result dialog. The match points will be listed, press [F4](OK) to identify selected point and back to Stakeout screen. (If the input is wildcard "\*", the program will show all the points of the current job.) × 2


B:

If there is no match point in the job, the program prompts"Pt. not found!". And then go in Find Point In Job screen. User can input a point or select a point from another job and then back to Stakeout screen.

4 After finishing setting stakeout point, start staking out.








- \*\*: The settings of job, station and orientation have been elaborated in detailIn the previous chapters, here is no longer repeat. Refer tochapters"Setting The Job Setting The Station Setting The Orientation".
- ※<sup>2</sup>: Unlike the other place's points list, the stakeout points are ordered by time.In the stakeout points list, the newest point is at the back and the fix point is in the front ofmeasured point. But in the other points list, the newest point is at the back and the measured point is in the front offix point.

#### Manual input stakeout point

Press key [Coord.] or [SO-PT] to manual input stakeout point coordinates and then continue staking out.

### [Coord.]:

Press [Coord.] and then input a target point's coordinates. Saved this point into job and continue staking out.




# [SO-PT]:

Press [SO-PT] to input a stakeout point without point name and being saved into job.

Steps	Key	Display
① Press [F4] (↓) to view the third page of soft keys.	[F4]	Search       :       * □         Pt.       :       5 ♠ □         T. H       :       1.500 m 1         △Hz       :       -13° 29′ 60″         △ □       :
② Press [F2](SO-PT) to go	[F2] +	[SO-Input data]
to SO-Input data screen. Input the coordinates of stakeout point. After input one item, the curser will move to next input item.	Input point name and coordinates + [ENT]	N : 0.000 m E : 0.000 m Z : 0.000 m
(3) After finishing inputs, press [F4](OK) to save the data. And then back to Stakeout screen. Start to stakeout the input point. The program will name this point DEFAULT automatically. **1**  ***: [SO-PT]: The input point of the program is approximately to be a provided by the point of the program is approximately to be a provided by the point of the program is approximately to be a provided by the program is approximately to be a provided by the provided b	won't he cave	[Stakeout] 1/3 Search : DEFAULT  Pt. : 5 ← 1.500 m 1  △Hz : ← -13° 29′ 60″  △  :  ALL DIST REC ↓

### **6.2 Polar Stakeout Mode**




The meanings of the differencesin the Polar Stakeout mode:

 $\triangle$ Hz Difference in direction:If the measured point is located in the right side of stakeout point, the value is positive.


△ Difference in horizontal distance: If the measured point is farther than stakeout point, the value is positive.

 $\triangle$  Difference in height: If the measured point is higher than stakeout point, the value is positive.

Steps	Key	Display
① Set all the points that are readied to stake out. Select one stakeout point through search the point name in the job.		Search       :       * □         Pt.       :       5 ♠ □         T. H       :       1.500 m 1         △Hz       :       -         13° 39′ 10″       -         △ □       :       -         ALL       DIST       REC




direction of the prism need to move. 6 Move the prism according to the direction of the arrow to make the value of  $\triangle$ equal 0m. Arrows Meaning: [Stakeout] 1/3 ↓ : Move the prism close to Search Pt. the station. T. H 2.000 m 1 ↑: Move the prism far away 0° 00′ 00″ ∠Hz the station. 0.000 m -0.309 m In the process of staking out, ALL REC using the Repeat Measurement or Tracking Measurement, the calculation of the differences between measured point and stakeout point can be displayedin real time and convenient. (7) It means the current prism position is effective stakeout point while both the $\triangle$ Hz and [Stakeout] 1/3 Search  $\wedge =$  are 0. Pt. T. H 2.000 m 1 0° 00′ 00″ ∠Hz  $\triangle$  **I** Display as dig or fill 0.000 m -0.309 m data. ↓ : The value expresses the depth of needed to dig. ↑: The value expresses the height of needed to fill.



## 6.3 Orthogonal to StationStakeout Mode

Use longitudinal difference and perpendicular difference to indicate the position differences of stakeout point and current prism position.





The meanings of the differencesin the Orthogonal to Station Stakeout Mode:

 $\triangle$ Length Difference in longitudinal distance: If the measured point is farther than stakeout point, the value is positive.

 $\triangle$ Trav. Difference in perpendicular distance: If the measured point is located in the right side of stakeout point, the value is positive.


Steps	Key	Display
① Press [PAGE] to show Orthogonal to StationStakeout Mode in page 2/3. Set the stakeout point. The stakeout point can be found in the job through inputting point name in the search item.	[PAGE]	[Stakeout]       2/3       ♣       ♠         Search       :       *       ♥         Pt.       :       6       ♠       ♠         T. H       :       1.500 m       1         △Length:            △Trav.       :           △Z/H       :           ALL       DIST       REC       ↓





### **6.4 Cartesian Stakeout Mode**

Stake out point based on the Cartesian coordinate system. The deviation values are the coordinate differences.





The meanings of the differences in the Cartesian Stakeout Mode:

 $\triangle$ Y/E The difference in East coordinate between measured point and stakeout point.

 $\triangle$ X/N The difference in North coordinate between measured point and stakeout point.

Steps	Key	Display
(1) Press [PAGE] to show Cartesian Stakeout Mode in page 3/3. Set the stakeout point. The stakeout point can be found in the job through inputting point name in the search item.	[PAGE]	[Stakeout]       3/3       ▲ □         Search       :       * □         Pt.       :       5 ♠ □         T. H       :       1.500 m 1         △ Y/E       :          △ X/N       :          △ Z/H       :          ALL       DIST       REC       ↓







# 6.5 [Polar]

Press [Polar], then input the polar stakeout elements: Azimuth and Horizontal distance. Start to stake out after finishing inputs of Azimuth and Horizontal distance.

Steps	Key	Display
① Press [F4](↓) twice to view the second page soft keys.	[F4]	Search       :       * □         Pt.       :       5 ♠ □         T. H       :       1.500 m 1         △Hz       :       -13° 29′ 60″         △ □       :
② Press [F1](Polar) to show the dialog as shown in figure.	[F1]	[Polar Stakeout]  Pt. : Azimuth :  : OK
③ Input the stakeout point's name, azimuth and horizontal distance. Press [ENT] to confirm every input and move the cursor to next input item. Press [F4](OK) to go to Polar Stakeout screen after finishing all inputs. ※¹	Input point name, azimuth and horizontal distance + [ENT] + [F4]	[Polar Stakeout]  Pt. : P001 Azimuth : 135° 33′ 23″  : 10.015 m







# 7. Resection

Resection measurement is an application used to determine the coordinate of the instrument station by measuring multiple known points. A minimum of 2 and a maximum of 5 known points can be used to determine the station. It should be used at least 2 known points by distance measurement or at least 3 known points by angle measurement.

Steps	Key	Display
① Select "Program" from the [Main Menu] window, press [F3] or number key [3] to enter the Resection application.	[F3]	[Program]       1/2 ▼         F1       Surveying       (1)         F2       Stakeout       (2)         F3       Resection       (3)         F4       Tie Distance       (4)         F1       F2       F3       F4
② Press [F1] in the [Resection] window to set the job.	[F1]	[Resection]  [] F1 Set Job F2 Set Error Limits F4 Start  F1 F2 F4
③ In [Set Job] window, press [F1] (List) to select a job in memory or press [F2] (New) to new a job. Then press [F4] (OK) to next step.	[F4]	[Set Job] Job : DEFAULT  Operator: Date : 20150515 Time : 14:10:20  List New OK



[F2] (REC) to record an angle. Distance measurement: [F1] (ALL) or [F1] + [F2] (DIST + REC). [Resection-Target PT] 1 (9) When finish a known Pt. 1.500 m Т. Н. point measurement, press [F2] (NEXT PT) to start next [F2] known point measurement. Find List Repeat steps (7) and (8). Coord. **Back** 10 If the measured known [Resection-Obserrve] Pt. points are enough, [Result] 1.500 m Т. Н. will display on the screen, 177° 55′ 56″ HA then press [F3] (Result) to 89° 15′ 12″ VA 16.132 m enter the [Station Coordinate] to view station result. NEXT PT Result Press [F1] (Back) back to a Press [F3] (Result) to enter the [Station new known point Coordinate to view result. measurement. [Station Coordinate] DEFAULT Station : 1.000 m Press [F2] (errors) to display IH. -7.422 m Y0/E0 standard deviation. X0/N0 10.628 m Z0/H0 1.464 m Press [F4] (OK) to set the Back **Errors** coordinate station and instrument height. Display standard deviation:



 $\aleph^1$ : The known points can be called from the memory through the [Find], [List] or manually entered used [Coord.].

### 8. Tie Distance

Tie Distance is an application used to compute slope distance, horizontal distance, height difference and azimuth of two target points which are either measured, selected from the memory, or input using the keypad.


The user can choose between two different methods:

Polygonal: P1-P2, P2-P3, P3-P4

• Radial: P1-P2, P1-P3, P1-P4


Start Tie Distance application through "Main Menu"→"Program"→"Tie Distance".


### 8.1 Polygonal




While Polygonal tie distance measuring continuous points, the new tie distance's first point will usethethe previous one tie distance's second point(P1-P2 \, P2-P3 \, P3-P4\dots).

Steps	Key	Display
① Press [F4] in the Program  Menu to go to Tie Distance application.	[F4]	[Program]       1/2       ▼         F1 Surveying       (1)         F2 Stakeout       (2)         F3 Resection       (3)         F4 Tie Distance       (4)         F1 F2 F3 F4







# 8.2 Radial



While Radial tie distance measuring continuous points, the new tie distance's first point continues usingthethe previous tie distance's first point(P1-P2、P1-P3、P1-P4······).

Steps	Key	Display
① Press [F4] in the Program  Menu to go to Tie Distance application.	[F4]	[Program]       1/2         F1 Surveying       (1)         F2 Stakeout       (2)         F3 Resection       (3)         F4 Tie Distance       (4)         F1 F2 F3 F4
② After finishing setting job, station and orientation, press [F4] in the Pre-Setting menu to go to Select Tie Distance Mode screen.	[F4]	[Tie Distance]  [*] F1 Set Job (1)  [*] F2 Set STA (2)  [*] F3 Set B.S. (3)  F4 Start (4)  F1 F2 F3 F4





# 9. Area

Area is an application used to calculate the polygon areas to a maximum of 20 points which connected by straights. The target points coordinate can be measured, selected from memory or entered via keypad in same direction. And the following three methods can be alternately performed. The calculate area is projected onto the horizontal plane (2D).







Figure 9.1 Area Diagram

- PO Instrument Point
- P1 Start Target Point
- P1~P5 Target Point
- a Perimeter, polygonal length from start point to the current measure point.
- S Calculated area always closed to the start point P1, projected onto the horizontal plane.

Steps	Key	Display	
① Select "Program"		[n 1 0/0	
from the [Main		Program 2/2	▼
Menu] window, then	[PAGE]	F1 Area	(5)
press [PAGE] switch	+	F2 Remote Height	(6)
to second program	[F1]	F3 COGO	(7)
list and press [F1] or	or	F4 Road	(8)
number key [5] to	[5]	F1 $F2$ $F3$ $F4$	4
enter the Area		-	
application.			







※ In [Area Result] window:

Press [F1] (New Area) to restart a new Area application.

Press [F2] (Graph) to show the area graph projected onto the horizontal plane.


Press [F4] (Add PT) to return the current Area application and continue operation.

Press [ESC] to exit the Area application.

※In all of the above operation, press [ESC] to return to the previous screen.

# 10. Remote Height

Remote Height is an application used to measure the height to the target (such aselectriccable, bridge, etc.) where can't be set prism.




Prism High Known

If the high of prism is known, the calculation formula of the remote height is:

$$H = S * \cos \alpha_1 * \tan \alpha_2 - S * \sin \alpha_1 + V$$

- H Height difference between the base point and the remote point
- V Prism High
- α<sub>1</sub> Vertical angle to prism
- α<sub>2</sub> Vertical angle to target





## 10.1 Prism High Unknown

If the high of prism is unknown, the calculation formula of the remote height is:

$$H = S * \cos \alpha_1 * \tan \alpha_2 - S * \sin \alpha_1 * \tan \alpha_3$$

- H Height difference between the base point and the remote point
- V Prism High
- S Slope distance between instrument and prism
- α<sub>1</sub> Vertical angle to prism
- α<sub>2</sub> Vertical angle to target point (remote point)
- α<sub>3</sub> Vertical angle to base point





### 11. COGO

COGO(Coordinate Geometry)is an application used to perform coordinate geometry calculations by the preset conditions such as , coordinates of points, bearings between points and distance between points.

The COGO calculation methods include:

- ♦ Inverse and Traverse
- ♦ Intersections
- ♦ Offset
- ♦ Extension

### 11.1 Traverse

Use the traverse subapplication to calculate the plane coordinate of a new pointusing the bearing and distance from a known point. Offset is optional.




Figure 11.1 Traverse Diagram


### Known


- PO known point
- a Direction from P1 to P2
- d Distance between P1 and P2
- d1 Positive offset to the right
- d2 Negative offset to the left


#### Unknown

- P1 COGO point without offset
- P2 COGO point with negative offset
- P3 COGO point with positive offset

Steps Key	Display
-----------	---------







- ※ In all of the above operation, press [ESC] to return to the previous screen.
- The result point is plane data.

## 11.2 Inverse

Use the inverse subapplication to calculate the distance, direction, height difference between two known points.




Figure 11.2 Inverse Diagram


## Known


- PO First known point
- P1 Second known point

### Unknown

- a Direction from P0 to P1
- S Slope distance between PO and P1
- d1 Horizontal distance between P0 and P1
- d2 Height difference between P0 and P1

Steps	key	Display
1 In the [Traverse & Inverse] screen, press [F1] or [1] to enter the Inverse subapplication.	[F1] or [1]	[Traverse&Inverse] F1 Inverse (1) F2 Traverse (2)  F1 F2





- ※ In all of the above operation, press [ESC] to return to the previousmenu.
- X The result point is plane data.

# 11.3 Bearing-Bearing Intersection

Use the bearing-bearing (BRG-BRG) subapplication to calculate the intersection point of two lines. A line is defined by a point and a direction.






Figure 11.3 BRG-BRG Diagram

Known	
P0	First known point
P1	Second known point
a1	Direction from P0 to P2
a2	Direction from P1 to P2
Unknown	
Р3	COGO point





- ※ In all of the above operation, press [ESC] to return to the previousmenu.
- \* The result point is plane data.

# 11.4 Bearing-Distance Intersection

Use the bearing-distance (BRG-DST) subapplication to calculate the intersection point of a line and a circle. The line is defined by a point and a direction. The circle is defined by the center point and the radius. The result may be have 1 intersection point, may be have 2 points, or may be have no one.




Figure 11.4 BRG-DST Diagram


## Known

- PO First known point
- P1 Second known point
- a1 Direction from P0 to P2 or P3
- r Radius, as the distance from P1 to P2 or P3

# Unknown

- P2 First COGO point
- P3 Second COGO point

Steps	key	Display
① In the [Intersection] screen, press [F2] or [2] to enter the BRG-DST subapplication.	[F2] or [2]	[Intersection]         F1 BRG-BRG       (1)         F2 BRG-DST       (2)         F3 DST-DST       (3)         F4 LNLN       (4)         F1 F2 F3 F4
② Input the name of first point in "PT1" field.  ※ There are four ways to get the known point for BRG-DST	Input name of first point	[BRG-DST] Input data!  PT1 : 8 AZ1 : 0° 0′ 0″  PT2 : 9 HD2 : 0.000 m  Meas. Result Find ↓



[BRG-DST Result] and	d
press [F4](REC) to save	e
the point.	
Press [F1] to switch to	О
view results.	

<sup>※</sup> In all of the above operation, press [ESC] to return to the previousmenu.

### 11.5 Distance-Distance Intersection

Use the distance-distance (DST-DST) subapplication to calculate the intersection point of two circles. The circles are defined by the known point as the center point and the distance from the known point to the COGO point as the radius. The result may be have 1 intersection point, may be have 2 points, or may be have no one.




Figure 11.5 DST-DST Diagram

#### Known


- P1 First known point
- P2 Second known point
- r1 Radius, as the distance from P1 to P3 or P4
- r2 Radius, as the distance from P2 to P3 or P4

### Unknown

- P3 First COGO point
- P4 Second COGO point

<sup>\*</sup> The result point is plane data.

Steps	key	Display
① In the [Intersection] screen, press [F3] or [3] to enter the DST-DST subapplication.	[F3] or [3]	[Intersection] F1 BRG-BRG (1) F2 BRG-DST (2) F3 DST-DST (3) F4 LNLN (4) F1 F2 F3 F4
② Input the name of first point in "PT1" field.  ※ There are four ways to get the known point for DST-DST calculation. Please refer to the step ② in the "COGO Traverse".	Set first point	[DST-DST] Input data!  PT1 : 8 HD1 : 0.000 m  PT2 : 9 HD2 : 0.000 m  Meas. Result Find ↓
③ Move the focus to "HD1" by using [▼] key and input the first radius after set first point.	[▼] + Input first radius	[DST-DST] Input data!  PT1 : 8 HD1 : 3.152 m  PT2 : 9 HD2 : 0.000 m  Meas. Result Find ↓
④ Move the focus to "PT2" by using [▼] to setting second point.	[▼] + Set second point	[DST-DST] Input data!  PT1 : 8 HD1 : 3.152 m  PT2 : 9 HD2 : 0.000 m  Meas. Result Find



- ※ In all of the above operation, press [ESC] to return to the previousmenu.
- X The result point is plane data.

# 11.6 Line-Line Intersection

Use the line-line (LNLN) subapplication to calculate the intersection point of to lines. A line is defined by two points.




Figure 11.6 LNLN Diagram


### Known

- P1 First known point
- P2 Second known point
- P3 Third known point
- P4 Fourth known point
- L1 Line from P1 to P2
- L2 Line from P3 to P4

## Unknown

P5 COGO point

Steps	key	Display
		=   /



- ※ In all of the above operation, press [ESC] to return to the previousmenu.
- \* The result point is plane data.

# 11.7 Distance-Offset

Use the distance-offset (DistOff) subapplication to calculate the foot point (COGO point) coordinates of offset point to baseline, the baseline is defined by two known points, and the longitudinal and offset distance of the offset point in relation to the line.




Figure 11.7 DistOff Diagram


# Known

- P1 Start point
- P2 End point
- P3 Offset point

# Unknown

- d1  $\triangle$ Line
- d2  $\triangle$ Offset
- P4 COGO point (foot point)

Steps	key	Display
1 In [COGO Menu] screen, press the [F3] or number key [3] enter the [Offsets] screen, then press [F1]	[F3] or [3]	[COGO Menu]  F1 Traverse&Inverse (1)  F2 Intersection (2)  F3 Offsets (3)  F4 Extension (4)
or [1] enter the DistOffsubapplication.		F1 F2 F3 F4



- ※ In all of the above operation, press [ESC] to return to the previousmenu.
- X The result point is plane data.

## 11.8 Set Point

Use the Set Point (Set Pt) subapplication to calculate the coordinate of a new point in relation to a line from known longitudinal and offset distance.




Figure 11.8 Set Point Diagram


# Known

- P1 Start Point
- P2 End Point
- d1  $\triangle$ Line
- d2  $\triangle$ Offset

### Unknown

P3 COGO point

Steps	key	Display	
(1) In the [Officete]		[Offsets] F1 DistOff (1)	
(1) In the [Offsets] screen, press [F2] or [2] to enter the Set Point	[F2] or [2]	F2 Set Pt (2)	
subapplication.		F1 F2	



- ※ In all of the above operation, press [ESC] to return to the previousmenu.
- \* The result point is plane data.

# 11.9 Extension

Use the Extension subapplication to calculate the coordinate of extended point from a known baseline.




Figure 11.9 Extension Diagram


## Known

- P1 Baseline Start Point
- P2 Baseline End Point
- L1, L2 Extension Distance

## Unknown

P2, P4 Extended COGO Point

Steps	Key Display		
① In the [COGO Menu] screen, press	[F4]	[COGO Menu] F1 Traverse&Inverse F2 Intersection	(1) (2)
the [F4] or number key	or [4]	F3 Offsets F4 Extension	(3) (4)
[4] enter the [Extension] screen.		F1 F2 F3	F4




Station	

- $\ensuremath{\mathbb{X}}$  In all of the above operation, press [ESC] to return to the previousmenu.
- $\divideontimes$  The result point is plane data.

# 12. Road

Using this program, user can simplely define a straight line, circular curve or transition curve as reference, to do surveying or staking out.


Setting job, setting station and setting backsight must be done before road define and staking out.



# 12.1 Road Manage

User can create some different roads. The data between different roads is individual.

Steps	Key	Display
① Pressing key [F4] enter road function menu. For job setting, station setting and BS setting can refer early content.	[F4]	[Road]  [*] F1 Set Job (1)  [*] F2 Set STA (2)  [*] F3 Set B.S. (3)  F4 Start (4)  F1 F2 F3 F4
② Pressing key [F1] enter road manage.	[F1]	[Road]    F1  Road Manage



## 12.2 Horizontal curve definition

There are two ways to define the horizontal curve: one is 'elements method', another is 'intersection method'.


NOTE: Max amount of items of horizontal curve is 30.

### Using elements method define horizontal curve.

**Elements method** constists of the following elements: start point, straight line, curcular curve and transition curve.


### Straight line

The straight line can be defined when start point or other type of element have been defined.




Straight line includes azimuth and distance, and the distance should nobe negative.

### Circular curve



Curcular curve includes radius and arc length. The rules of radius definition: Along the arc direction, radius is positive if arc is clockwise; radius is negative if arc is anti-clockwise. Arc length should not be negative.


### > Transition curve





Transition curve includes the minimum radius and arc length. The rules of radius are same to curcular curve radius. Arc length should no be negative.

### Steps:

Steps	Key	Dienlay
Steps	кеу	Display
	[F4]	[Road]
① Pressing key [F4] enter Road functions menu.		[*] F1 Set Job (1) [*] F2 Set STA (2) [*] F3 Set B.S. (3) F4 Start (4)  F1 F2 F3 F4
② Pressing key [F2] enter horziontal curve list.	[F2]	[Road]








# Using intersection method define horizontal curve.

The intersection point includes coordinate, radius, parameter A1 and A2 of transition curve. The radius and A1, A2 should not be negative. If radius not being zero, it will insert an arc with input radius between current point and next point. If A1, A2 not being zero, it will insert and transition curve with sepecified length between straight line and the arc.

Don't mix the intersection point with straight line, circular curve or transition curve, otherwise the calculation will not be correct.




Follow is the intersection method for definition of horizontal curve steps.

#### Steps:

Steps	Key	Display	
		[Road]	
① Pressing key [F2] enter Horziontal curve editing.	[F4]	[*] F1 Set Job [*] F2 Set STA [*] F3 Set B.S. F4 Start	(1) (2) (3) (4)
		F1 F2 F3	F4





 $\aleph^1$ : When input A1, A2 according to curve length L1, L2, use follow formula to calculate A1, A2:


$$A_1 = \sqrt{L_1 \cdot R}$$

$$A_2 = \sqrt{L_2 \cdot R}$$

<sup>№2</sup>: Cannot delete start point.

## 12.3 Vertical curve definition


Vertical curve consist of a set of intersection points. Intersection point includes chain number, elevation and curve length. The curve length of start point and last point must be zero.




NOTE: Max amount of items of vertical curve is 30.

# Steps:

Steps	Key	Display
① Pressing key [F4] enter Road functions menu.	[F4]	[Road]
		[*] F1 Set Job (1) [*] F2 Set STA (2) [*] F3 Set B.S. (3) F4 Start (4)
		F1 F2 F3 F4





#### 12.4 Road Stakeout


User can do road stakeout according to specific chain number and offset.

Before doing stakingout, user must define horizontal curve. If need calculating elevation, user must define vertical curve either.

The rules of stakeout data are defined as shown below:


Offset left: the horizontal distance between left pile and center line; Right: the horizontal distance between right pile and center line.

Elevation left(right): the vertical distance between lefit(right) pile and center line.



In doing stakeout, center pile should be done first, then left and right pile. Like point stakeout, there are three methods to do stakeout:

Method	Definition	Display
Polar staketou	<ul> <li>△Hz</li> <li>Direction difference:</li> <li>Positve if measuring point being right side of target point.</li> <li>△</li> <li>Horizontal distance difference: Positive if measuring point far away target point.</li> <li>△</li> <li>Height difference: Positive if measuring point above of target point.</li> </ul>	[Road Stakeout] 1/3  Pt. : K+12.0  T. H. : 2.000 m  AHz : — 13° 39′ 10″  ALL DIST REC EDM




User can use [PAGE] key to switch method between these 3 methods. Doing stakeout can refer to Point stakeout.

#### Steps

Steps	Key	Display
① Pressing key [F4] enter Road functions menu. Before doing stakeout, job seting, station seting, BS seting should be done.	[F4]	[Road]  [*] F1 Set Job (1)  [*] F2 Set STA (2)  [*] F3 Set B.S. (3)  F4 Start (4)  F1 F2 F3 F4
② Pressing [F4] enter road stakeout.	[F4]	[Road]

③ Input road parameters and press [F4] entering chain parameters editing window.	[F4]	Road SO para. 1/2  StartC.: 0.000 m  Incre.: 20.000 m
4 Input chain parameters and press [F4] to next window.	[F4]	Road SO para. 2/2 OffsL: OffsR: TgthL: TgthR: TgthR: OK
⑤ Program shows chain's paramters that user has input. Press [←][→] to left or right pile. Press [↓][↑] to increase or decrease chain number. Press [Edit] to edit the parameters.	[F4]	Road SOCenter   Chain : 0.000 m   Offset: 0.000 m   HV : 0.000 m   T. H. : 2.000 m
6 Press [CALC] to see the result point coordinate.If need to calculate other chain point, press [ESC] to return.	[F3]	Road S0—Right Pt.: K+80.0 N: 113.170 m E: 462.883 m Z: 12.079 m  REC Stakeout



**Note:** If has saved road data, next time user can directly go to the road program without inputting road data again.

# 13. Stakeout Reference Element


Stakeout Reference Element is used for making Reference Element stakeout and check easier, such as building, road cross section, or simple excavation. User can define a Reference Line/ARC, according to measuring result, to calculate out the deviated difference& elevation difference between measuring point and reference line/arc. Reference element function include:

- ♦ RefLine
- ♦ RefArc

#### 13.1 RefLine

User need to define a reference line through a known base line. The reference line can be shifted in longitudinal, horizontal, vertical direction, or rotate around the first base point as needed. The line after shift is as reference line, all observed data refer reference line. User can choose the first point, second point or mean point in refline direction as refered elevation point.

Refline schematic diagram:



#### Known

L1 Baseline

P1 First point

P2 Second point

d1 Offset

Rotate r+

#### Unknown

Measure point p

d3  $\Delta$  Length

d4

 $\Delta$  trav.


L2 Reference Line


Р3 First reference point


Ρ4 Second reference point


d2 Line

P0 **STA** 









#### \*\* Ref. Hgt options:

PT1 : The elevation value of defined first point

PT2 : The elevation value of defined second point


Equal : Average value of defined two endpoints' elevation

None : Not perform elevation difference calculation

※ In above operation, press [ESC] to return to previous menu

#### Stakeout Grid


Steps	Key		Dis	splay	
① In the interface of [Reference Line-Main], press [F1] (Gird) to enter the [Grid Definition] .	[F1]	Length: Enter value Offset: Line: Height: Rotate: Grid M		ine-Main] 360.558 shift line 5.000 2.000 10.530 1° 02′ 03 Stake Segment	5 m ! O m O m 6 m



※ In above operations, press [ESC] to return to previous menu.

#### Measure Line&Offset

Steps	Key	Display
① In interface of [Reference Line-Main] , press [F2] (Meas.) to enter [Measure Line&Offset] interface.	[F2]	[Reference Line-Main] 1/2   Length: 360.555 m   Enter values to shift line! 0ffset:   Offset: 5.000 m   Line: 2.000 m   Height: 10.536 m   Rotate: 1°02′03″   Grid Meas.   Stake ↓   NewBL Zero   Zero Segment
2 There are many methods to obtain points for calculating Line&Offset A: Input the name of point, press [F1](ALL) to measure current point, calculate and display the offset to refline, then save this point data.	Input point name + [F1]	A: Get the target point by measure.  [Measure Line&Offset] PT. : 4 T. H. : 2.000 m Δ Length: 3.369 m Δ trav. : 1.147 m Δ  : 1.256 m  ALL DIST REC




※ In above operation, press [ESC] to return to previous menu.

# Orthogonal stakeout

Steps	Key	Display
In [Reference Line-Main] screen, press [F3](Stake) enter [Orthogonal stakeout] to input stakeout values.	[F1]	[Reference Line-Main] 1/2 Length: 360.555 m Enter values to shift line! Offset: 5.000 m Line: 2.000 m Height: 10.536 m Rotate: 1°02′03″ Grid Meas. Stake  NewBL Zero Segment ←
② In interface of [Orthogonal Stakeout] use [▲]\[▼] to select input box, use keyboard to set every offset parameters, then press [F4](OK) to enter orthogonal stakeout.	+ Input parameters +	[Orthogonal Stakeout] Enter orth. stakeout values! PT. : 3 T. H. : 2.000 m EndW. OS: 9.876 m Transverse: 8.765 m Z : 7.654 m Back Reset OK
point through [F1](ALL) or [F2]+[F3](DIST+REC).	[F1] or [F2]+[F3]	[Orthg. Stakeout] 1/2 PT. : 3 T. H. : 2.000 m  △ Hz : → 1° 02′ 03″  △ △ : ↑ -146.573 m  △ △ : ↑ -15.842 m  All DIST REC  NEXT PT EDM Back

## Segment stakeout

Steps	Key	Display
① In [Reference Line-Main] screen, press [F4](↓) and Press [F3] to enter [Segment Definition] interface	[F4]	[Reference Line-Main] 1/2 Length: 360.555 m Enter values to shift line! Offset: 5.000 m Line: 2.000 m Height: 10.536 m Rotate: 1° 02′ 03″ Grid Meas. Stake  NewBL Zero Segment    NewBL Zero   NewBL   NewBL



<sup>※¹</sup> Segment options:

Start : Misclosure at the start point EndPt : Misclosure at the end point


Equal: Divide Reference Line equally into several pieces

※ In above operation, press [ESC] to return to previous menu.

#### 13.2 RefArc

RefArc can be defined through "Centre, Start Point" or "Start&End Pt, Angle", and you can calculate Line&Offset of point to refarc. The application program allow user define a refarc and finish below task about refarc:

• Measure Line&Offset RefArc schematic diagram:



## Known

- L1 RefArc
- O Centre
- PO STA


# Unknown


- p Measure point
- d1  $\Delta$ Line
- d2  $\Delta$ Offset


- P1 Start PT
- P2 End PT

## Centre, Start PT

Steps	Key	Display	
		[Program]	3/3
		F1 Reference Element	(9)
(1) In [Program] main	[F1] or		
menu 3/3 page, press	[9]		
[F1] or numeric [9], set		F1	
job, B.S. and enter			
[Reference Line/ARC]		[Reference Line/ARC]	
menu, then press [F2] or	[F2]	F1 RefLine	(1)
numeric [2] to enter	or	F2 RefArc	(2)
RefArc function.	[2]		
		F1 F2	









¾¹ When the centre and start point coincide, the system error reporting "invalid target data, please input again, select "yes" or press [ESC], return to the measurement center interface, and restart the definition of arc.


※ In above operation, press [ESC] to return to previous menu.

## Start&End Pt, Angle

Steps	Key	Display
1) Press the [F1] or the numeric key [9] in the 3/3 page of the main menu, set the job, B.S and enter [Reference Line/ARC] menu, then press the [F2] or the numeric key [2] to enter the definition of RefArc.	or	[Program] 3/3 F1 Reference Element (9)  F1  [Reference Line/ARC] F1 RefLine (1) F2 RefArc (2)
② In [Define Ref-ARC method] screen, press the [F2] or the numeric key [2] to choose the [Star&End Pt, Angle ], and measure start point.	or	[Define Ref-ARC method] F1 Centre, Start Point (1) F2 Start&End Pt, Angle (2)  F1 F2










 $\divideontimes^1$  AZ1 and AZ2 are start point, end point tangent azimuth respectively . If the input data is not in conformity with the requirements, the instrument will report "invalid target data, please input again", you can select "yes" or press the [ESC] to return to the interface of starting point measurement, start to define arc.

In above operation, press [ESC] to return to previous menu.

#### Measure Line&Offset







<sup>★1</sup> Result of Line&Offset:


 $\Delta$ Line: Measuring point relative to the start point of arc , if it is beyond the reference arc , $\Delta$ Line will be negative, and on the contrary is positive;


 $\Delta$ Offset: the offset of the measuring point with respect to the arc in the direction of the radius.If the measuring point is in the circle, the  $\Delta$ Offset will be positive, and on the contrary is negative.

△ ■: the elevation difference between measuring point and starting point; If it is higher than start point, it will be positive, and on the contrary is negative.
※ In above operation, press [ESC] to return to previous menu.

# 6. File manage

File manager contains all functions of input data, edit data and view data.






# 1. Job


- All kinds of measurement data are saved in the selected job. Such as Fix Pt., Meas. PT and so on.
- The function can new a job, select a job and delete a job.
- > The definition of the job contains the inputing of Job's name and Operator.


## 1.1 Select a Job

Steps	Key	Display	
① Press [F1] in the menu of Job Manager to enter menu of job function.	[F1]	[Job Manage] 1/2 F1 Job F2 Fix Pt. F3 Meas. PT F4 Code F1 F2 F3	(1) (2) (3) (4)



#### 1.2 New a Job






[Job]: The name of job inputted arbitrarily by the operator and saving data to the file after this.

[Operator]: The name of operator and it can have the default value.

[Note1] and [Note2] describe the situation of the project and they can have the default values.

If the job name you inputted exists, the program will give a prompt that Job exists, use another job name.

## 1.3 Delete a job



# 2. Fix Pt.

The function can view, edit and delete the fixpoints in all jobs.

Steps	Key	Display	
① In the menu of Job Manager, press [F2] to enter the interface of Fix Pt. function.	[F2]	[Job Manage]     1/2       F1     Job     (1)       F2     Fix Pt.     (2)       F3     Meas. PT     (3)       F4     Code     (4)       F1     F2     F3     F4	
2 The interface displays the fixpoints of the current job. Pressing the direction key of left or right can scan all fixpoints in the job.Press [F4] to switch to the second page' soft key.	[F4] + [F2]	[View FixPoint] 1/4  Job : J0B1  Pt. : 6 ←  N : 1.000 m  E : 1.000 m  Z : 1.000 m  Find New Edit   Delete Job ←	
③ Press [F2](Job) to enter the list of job, press the directon key of up or down to select the job which the viewed fixpoints exist, then press [F4] to make sure. ※ <sup>1</sup>	[F4]	[Select Job]  JOB1 * JOB2 JOB3 [SD] JOB4 [SD]  View New OK	
4) Program displays the data of fixpoint in the corresponding job. Press the direction key of left or right can view all fixpoints in the job.	[ <del>←</del> ]	[View FixPoint] 1/22  Job : JOB2  Pt. : P1 ◆  N : 2.000 m  E : 3.000 m  Z : 4.000 m  Delete Job	

# 2.1 Search Fix Pt.


Input the name of point or " $\ast$ " to view the fixpoints in the selected job.

Steps	Key	Display
① In the intertface of View FixPoint, pressing [F1] (Find) to enter the function of finding fixpoints.	[F1]	[View FixPoint]  Job : JOB1  Pt. : 6 ←  N : 1.000 m  E : 1.000 m  Z : 1.000 m
2) There appears a dialog as shown in the picture on the right. Input the name of point or the wildcard of "*", press [ENT] to make sure and press [F4] (OK) to find.	[ENT] + [F4]	[Find]  Job : JOB1  Pt. : 1
③ Displaying the dialog of finding result.  If the point exists in the job, the interface will display the coordinate information of the point.  If input the wildcard of "*", you can view all fixpoints by pressing the direction key of left or right.		[View FixPoint] 1/1  Job : JOB1  Pt. : 1 ←   N : 1.000 m  E : 1.000 m  Z : 1.000 m

# 2.2 Add Fix Pt.

Steps	Key	Display
① In the interface of View FixPoint, pressing [F2] (New) to enter the function of newingfixpoint. If you want to change the job which need to new points, you can press [Job] to select the target job.	[F2]	[View FixPoint] Job : J0B1 Pt. : 6 ♠ N : 1.000 m E : 1.000 m Z : 1.000 m  Find New Edit ↓
2 There appears a dialog as shown in the picture on the right. If want to back to the previous menu, you can press [F1] (Back).		[New FixPoint]  Job : JOB1  Pt. :  N :  E :  Z :  Back OK
③ Input the new name and coordinate of fixpoint, press [Ent] to finish inputing and press [F4] (OK) to save the fixpoint.  If the inputted point name exists in the memory, the program will give a prompt of whethe to overwrite, press [F4](Yes) to overwrite or press [F1](No) to cancle the operation.		[New FixPoint]  Job : JOB1  Pt. : 1  N : 100.000 m  E : 100.000 m  Z : 100.000 m  Back OK  PT exists!  If overwrite?  No Yes

4 After finishing newing a fixpoint, the program makes the point plus 1 automatically and you can continue to input other fix points, as shown in the picture on the right.Press [F1] (Back) or [ESC] to go back.



#### 2.3 Edit Fix Pt.

The function can edit the fixpoints in the memory.

Steps	Key	Display
① In the interface of View FixPoint, you can find the data of need to be edited by pressing the direction key of left or right or in the function of finding. If you want to change the job which the point needs to be edited, you can press [Job] to select the target job.		[View FixPoint] 7/22  Job : JOB1  Pt. : P7 ◆▶  N : 2.000 m  E : 3.000 m  Z : 1.000 m
2 Press [F3] (Edit) to enter the interface of Edit Fixpoint. The screen displays the point data. Input the new point's name and coordinate and press [ENT] to move the cursor to the next row. When the data doesn't need to be edited, you can press [ENT] directly.		[Edit FixPoint]  Job : JOB1  Pt. : P7  N : 2.000 m  E : 3.000 m  Z : 1.000 m

③ Press [F4] (OK) to save the edited data after finishing inputing. Program gives a prompt wheter to overwrite or not and press [F4] (OK) to overright and save.

[Edit FixPoint]

Job : JOB1

Pt. : P7

N : 12.000 m


E : 13.000 m

Z : 5.000 m

## 2.4 Delete Fix Pt.

Delete the selected fixpoint from the job.

Steps	Key	Display
① In the interface of View FixPoint, you can find the data of need to be deleted by pressing the direction key of left or right or in the function of finding, then press [F4] to switch to the second page of soft key. If you want to change the job which the point needs to be deleted, you can press [Job] to select the target job.	[F4]	[View FixPoint] 7/22 Job : J0B1 Pt. : P7 ◆▶ N : 2.000 m E : 3.000 m Z : 1.000 m  Find New Edit ↓  Delete Job
② Press [F1] (Delete) to start the function of deleting data, the interface as shown the dialog on the right.Press [F4] (OK) to delete data and press [F1] (No) to cancle the operation.	[F2]	If delete data? Data cannot recover!




# 3. Meas. Pt.

The measurement data in the job can be searched, displayed, and part of them can be deleted.

## 3.1 View the measurement data

Steps	Key	Display
① In the menu of Job Manager, press [F3] to enter the function of Meas.PT.	[F4]	[Job Manage] 1/2 ▼ F1 Job (1) F2 Fix Pt. (2) F3 Meas. PT (3) F4 Code (4)  F1 F2 F3 F4
2) The default viewed job is the current job in the program, if you want to view the measurement data in other jobs, please press [F1] (Job) to enter the list of job to select.	[F2]	[View Meas Pt] Job : DEFAULT Pt. : *
3 The default viewed points are all points in the job and using the vildcard character to stand for. If want to view a certain point, you can input the name of the point and	[F4]	[View Meas Pt] Job : DEFAULT Pt. : *




#### 3.2 Delete measurement data

The not good and the repeating measurement data can be deleted.

The station data and the last piece of data in the data items can not be deleted.

Steps	Key	Display
① After finding the measurement point data which need to be deleted, press [F1] to delete.	[F1]	[View Meas Pt] 1/28 ▼ Pt. : 6 Job : DEFAULT Type : Meas. HA : 223° 44′ 06″ VA : 88° 20′ 11″ Date : 2015.05.23  Delete Search
② The window of program prompts whether to delete or not.  Press [F4] to make sure to delete and press [F1] to cancle the operation.	[F4]	If delete data? Data cannot recover!




# 4. Code.

Here can make operations on the code library, such as newing, finding and deleting.

# 4.1 Input Code

Every code has a note and up to 8 characters attributes.



GSI-The introduction of code' attributes:


Code: Name of the code
Note: Additional annotation

Info1: The other editable information

• • • • • •

Info8: Other information


Steps	Key	Display	
① In the menu of Job Manage, pressing [F4] to enter the function of Code.	[F4]	[Job Manage] 1/2 F1 Job F2 Fix Pt. F3 Meas. PT F4 Code  F1 F2 F3	(1) (2) (3) (4)



# **4.2 View Code**

Steps	Key	Display
① In the menu of Job Manage, pressing [F4] to enter the function of Code.	[F4]	[Job Manage]       1/2       ▼         F1       Job       (1)         F2       Fix Pt.       (2)         F3       Meas. PT       (3)         F4       Code       (4)         F1       F2       F3       F4
② Press the direction key of left or right, you can view all codes one by one.		[View Code] 1/5 ▼ Code : TREE () Note : Info 1 : GREEN Info 2 : Info 3 : Info 4 :  Find New Delete
③ Press [F1] to enter the interface of Search Code. The default vaue is wildcard character, it stands for all codes.		[Search Code]  Code : *
4 Input the certain code name and input [F4] to start to search.	[F4]	[Search Code]  Code : C1


Searching result, if there are more than one codes matching the searching condition, you can view them one by one by pressing the direction key of left or right. If there is no code matches the condition, the program will give a prompt.



## **4.3 Delete Code**

Steps	Key	Display
① After entering the dialog of code function, press the direction key of left or right to delete the code which need to be deleted.  You can also press the key of [Find] to find the corresponding code.		[View Code] 1/5 ▼ Code : TREE ♠ Note : Info 1 : GREEN Info 2 : Info 3 : Info 4 : Find New Delete
<ul> <li>2 After finding the code need to be deleted, press [F4] and program will give a prompt whether make sure to delete.</li> <li>A: If the deleted code is finded by pressing the direction keys, after the code is deleted, the screen will display the next code. B: If the deleted code which</li> </ul>	[F4]	A:  [View Code] 1/4


finded by press the key of [Find], after the code deleted, the interface displays an empty code, it means that all fields are empty. If there is more than one code matching the finding condition, it will display the next code.



# 5. Memory Statistics

Display the information of the memory usage and format the memory.

Format the memory can delete all data of job, code and road. The setting of application also can be reset, please operate carefully.



## 7. Data Transfer

This function is doing data transmission between instrument and computer, or between instrument and removable device. This function includes 2 parts, import and export.

The data transmission between instrument and removable device must have U Disk plugged in.

**Note:** The machine supports up to 8G U disk read and write, when running the program, don't insert or pull out the U disk. If you pull out the U disk when the instrument checking it, the subsequent operations may cause error!

# 1. Data Import

Job:

User can use this function to transfer fixed points data or code data to instrument from computer via RS232 cable. User can also transfer fixed points data to instrument via UDisk.

Import: Fixed Points, Code


Method: RS232, UDisk

Format: CASS, GTS-7, CSV, GSI(For UDisk)


Target job that data been transfer to.

Source: Data file in UDisk (For UDisk)

Steps Display Key [Transfer] F1 Import Data (1) (1) In main (2)F2 Export Data [4] "4 menu,chooses Transfer" "Data Transfer" menu. F1 F2 [Import Data] [F1] F1 Fix Pt. (1) or F2 Code Data (2) Pressing [F1] or [1] [1] enters "Import Data".



**Total Station Manual** 



# 2. Data Export

User can use this function to transfer internal data (fixed points, measurement data, and code) from instrument to computer or udisk.

Export: Fixed points, measure data, and code.


Method: RS232C, UDisk.


Format: CASS, GTS-7 (For fixed point, UDisk)

HTF format, GSI format, GTS-7, CSV, CASS(For measure data, UDisk)

Job: Job needs to export.

Steps	Key	Display	
① In main menu, choose "4 Transfer" to enter "Data Transfer"	[4]	[Transfer] F1 Import Data (1) F2 Export Data (2)	
menu.  Pressing [F2] or [2] enters "Export Data".。	[F2] or [2]	F1 F2  [Export Data] F1 Job Data (1) F2 Code Data (2)  F1 F2	








# 8. Instrument Setting

# 1. General Setting

In Setting Menu, choose "1 General" to enter "General Setting".










#### **Fields of General Setting**

Field	Description
Light	Hight, Medium, Low, Off. 4 Levels of background light.
Contrast	1~9. Set the display contrast.
Trigger Key	Off: Disable trigger key.
	ALL: Disting and record.
	DIST: Only disting.
User Key 1	Configures 1 with a function from the FNC menu.
User Key2	Configures 2 with a function from the FNC menu.

Key Beep	The beep is an acoustic signal after each key stroke.					
	On: Enable beep.					
	Off: Disable beep.					
Sector Beep	<b>On:</b> Sector Beep sounds at right angles( $0^{\circ}$ , $90^{\circ}$ , $180^{\circ}$ , $270^{\circ}$ or					
	0, 100, 200, 300 gon).					
	Off: Sector Beep diabled.					
Tilt	On: Biaxial compensation enable.					
	Off: Tilting compensation disable.					
	X Only: Single axis compensation enable.					
Hz increment	<b>Right:</b> Set horizontal angle to clockwise direction measurement.					
	<b>Left:</b> Set horizontal angle to counter-clockwise direction measurement.					
V-Setting	<b>Zenith:</b> Zenith = $0^{\circ}$ ; Horizon = $90^{\circ}$ .					
	270° 90° 180°					
	<b>Horiz.0:</b> Zenith = $270^{\circ}$ ; Horizon = $0^{\circ}$ .					
	270° 0°					
	<b>Vert90:</b> Zenith = $90^{\circ}$ ; Horizon = $0^{\circ}$ ;					


Positive above horizon, negative below horizon.



**Slope:** Zenith  $45^{\circ}$  =100%; Horizon = 0%.

Positive above horizon, negative below horizon.

Exceed 300% shows "--.--%".



#### **Angle Unit**

Sets The units shown for all angular fields.

 $^{\circ}$   $^{\prime}$   $^{\prime\prime}$  Degree sexagesimal, 0 $^{\circ}$  to 359 $^{\circ}$  59'59".

GonGon, 0 gonto 399.999 gon.

MilMil, 0 to 6399.99mil.

The setting of the angle units can be changed at any time. The actual displayed values are converted according to the select unit.

#### Mini. Reading

Sets the number of decimal places shown for all angular fields. This is for data display and does not apply to data export or storage.

° ′ ″ :1" /5"/10"

Gon:0.0002/0.001/0.002

	Mil:0.005 / 0.02 / 0.05					
Dist. Unit	Sets the units shown for all distance and coordinate related fields.					
	Meter Meters [m].					
	US-ftUS feet [ft].					
	INT-ftInternational feet[fi].					
	ft-in1/8US feet-inch-1/8 inch [ft].					
Dist.Decimal	Setes the number of decimal places shown for all distance fields.					
	This is for data display and does not apply to data export or storage.					
	<b>3</b> Display distance with three decimals.					
	4Display distance with four decimals.					
Temp. Unit	Sets the units shown for all temperature fields.					
	°C Degree Celsius.					
	T Degree Fahrenheit.					
Press.Unit	Sets the units shown for all pressure fields.					
	hPAHecto Pascal.					
	mmHgMillimeter mercury.					
	inHgInch mercury.					
Code	Sets if the code will be used for one, or many, measurements.					
	Rec/Reset The code is cleared after ALL or REC.					
	Permanent The code remains after measurements.					
Auto-Off	<b>30min</b> Auto poweroff after 30min's no operation.					
	Off Disable auto-off.					

# 2. EDM Setting

See Chapter "3.2 EDM Setting".


# 9. Adjust and Tools

# 1. Adjust

#### Warning:

The following functions must be carried out under the guidance of professionals, if the operation is wrong, it may lead to the instrument can't work properly!

Through Main Menu → "6 Tools" → "1 Adjust", entering adjust menu, Like below:



# 1.1 View adjust parameters

In Tools Menu, choose "1 Adjust", and then press [F1] to enter "View adjust parameters".

Parameters include Vert.I.E and tilt sensor parameters.

	[View	Adjust	Para	am.]	
Vert.	I.E.:		93°	35 <i>′</i>	52 $''$
Xk	:			-0.8	3400
X0	:				9
Yk	:			1.	000
YO	:				0
					OK

# 1.2 Adjust Index Error

In Tools Menu, choose "1 Adjust", then press [F2] to enter "Adjust Index Error".

# Steps:


Steps	Key	Display
① After leveling the total station, aim at target with face left, then press [F4](OK).	[F4]	[Adjust Index Error] F1 reading: 342° 11′ 59″ F2 reading: Vert. I.E.: Take positive!!
② Aim at the same target with face right, and press [F4] (OK).	[F4]	[Adjust Index Error] F1 reading: 342° 11′ 59″ F2 reading: 191° 26′ 31″ Vert. I.E.:  Take reverse!
③ Program will show the result value, press [F4](OK) to save.	[F4]	[Adjust Index Error] F1 reading: 342° 11′ 59″ F2 reading: 191° 26′ 31″ Vert. I.E.: 93° 10′ 45″ Press OK to save.  OK

**Note:** If there is no special requirement, the compensator should be turned on before Index error correction.

# 1.3 Adjust Tilt X

Before compensating for the compensator, make sure that the indicator difference is recalibrated in accordance with 9.1.2 procedure in the closed compensator state.

First, place the instrument as picture shown below with collimator facing up. This will help screw A to adjust the inclination of the instrument.



In Tools Menu, choose "1 Adjust", and then press [F3] to enter "Adjust Tilt X". These are the calibaration of x-diretion of compensator's vertical axis.

Steps	Key	Display
1 Level instrument, focus on the reticle of collimator, record the vertical angle VO. Use fine tuning to set vertical angle to VO+3',focus on the reticle center accurately, wait for stable value,press [F4](OK).	[F4]	[Adjust Tilt X] HA : 10° 12′ 02″ VA : 81° 53′ 49″ Tilt : -117 F1 up 3′ OK
② Use fine tuning to set the vertical angle to V0-3', focus on the reticle center accurately, wait for stable value, press [F4] (OK).	[F4]	[Adjust Tilt X]  HA : 10° 12′ 02″  VA : 81° 59′ 50″  Tilt : -86  F1 down 3′  OK
③ Use fine tuning to set the vertical angle as V0, focus on the reticle center accurately.		
4 Reverse the telescope, use face right to focus on the reticle of collimator, record the vertical angle V1. Use fine tuning to set the vertical angle as	[F4]	[Adjust Tilt X] HA : 190° 25′ 38″ VA : 269° 23′ 45″ Tilt: 96 F2 up 3′ OK

V1-3',focus on the reticle center accurately, wait for stable value, pressF4(OK).		
(5) Use fine tuning to set the vertical angle as V1+3', focus on the reticle center accurately, wait for stable value, press [F4](OK).	[F4]	[Adjust Tilt X]  HA : 342° 11′ 59″  VA : 269° 29′ 46″  Tilt: 91  F2 down 3′  OK
6 After finishing, it will display the results, press [F4](OK), save and back to menu.	[F4]	[Adjust Tilt X]  HA : 342° 11′ 59″  VA : 269° 29′ 46″  Tilt : 100  Xk: 33.0859 X0: -55

**Note:** CoK (linear coefficient): If absolute value > 1.5, you need to re-calibrate; In the correction process by pressing the ESC key, will exit, holding compensator parameters unchanged.


# 1.4 Adjust Tilt Y

In Tools Menu, choose "1 Adjust", and then press [F4] to enter "Adjust Tilt Y". These are the calibaration of y-diretion of compensator's vertical axis.

Steps	Key	Display
① Level instrument, focus on the reticle of collimator, record the vertical angle V0. Use fine tuning to set vertical angle to V0+3',focus on the reticle center accurately, then turn the instrument counterclockwise 90 °,	[F4]	[Adjust Tilt Y] HA : 10° 12′ 02″ VA : 81° 53′ 49″ Tilt : -117 F1 up 3′ OK

wait for stable value, press [F4] (OK), and then turn 90 ° clockwise back to the original direction.  ② Use fine tuning to set the vertical angle to V0-3', focus on the reticle center accurately, then turn the instrument counterclockwise 90 °, wait for stable value, press [F4] (OK), and then turn 90 ° clockwise back to the original direction.	[F4]	[Adjust Tilt Y] HA : 10° 12′ 02″ VA : 81° 59′ 50″ Tilt : -86 F1 down 3′ OK
3 Use fine tuning to set the vertical angle as V0, focus on the reticle center accurately.		
delescope, use face right to focus on the reticle of collimator, record the vertical angle V1. Use fine tuning to set the vertical angle as V1-3', focus on the reticle center accurately, then turn the instrument counterclockwise 90°, wait for stable value, pressF4(OK), and then turn 90° clockwise back to the original direction.	[F4]	[Adjust Tilt Y] HA : 190° 25′ 38″ VA : 269° 23′ 45″ Tilt: 96 F2 up 3′ OK


**Total Station Manual** 



**Note:** CoK (linear coefficient): If absolute value > 1.5, you need to re-calibrate; In the correction process by pressing the ESC key, will exit, holding compensator parameters unchanged.

### 1.5 Instrument constant setting

In Tools Menu, choose "1 Adjust", and then press [F4 to enter "Const. Setting". Press [F4](OK) to save after editing the constants.



#### 1.6 Factory setting

In Tools Menu, choose "1 Adjust", and then press [5] to enter "Factory Setting".


If you need to reset the instrument parameters to factory state, you can use this function, press key [F4] (Yes) and then the instrument will auto power off.

# 2. System infomation

#### 2.1 View System Information

In Tools Menu, choose "2 Info." to enter "Info".

In this window, user can view detail information about the instrument, includes instrument type and SN, firmware version and date time.




**System Infomation** 

# 2.2 Set System Date

In system information window, press [F1] (Date) to enter "Date Setting" window. To set the date, input the new date string that in the format of tips, then press [F4] (OK) to save the new date.

For example: To set date "2015-11-11", input string "20151111", then press [F4] (OK) to save.




**Date Setting** 

# 2.3 Set System Time

In system information window, press [F2] (Time) to enter "Time Setting" window.

To set the time, input the new time string that in the format of tips, then press [F4] (OK) to save the new time.

For example: To set time"13:58:30", input string "135830", then press [F4] (OK) to save.



**Time Setting** 


# 2.4 Firmware Upgrade

#### Warning:


The following functions must be carried out under the guidance of professionals, if the operation is wrong, it may lead to the instrument can't work properly!

This function is prepared for the users to upgrade theinstrument software.

1. Input PIN code(82543), and then press key ENT, the instrument will be turned off.




 Connected to the computer through a serial cable, after installing the correct driver premise, open a HyperTerminal software, configure the correct serial port, it will "bits / sec" is set to 115200, "Data Flow Control" is set to "None" and press OK.




3. Press the power key of the instrumentin Hyper Terminal, shown as follows:


Note:Software upgrade operation must be carefulonce you select the instrument into the upgrade status; if press "3" in the picture below, you can also resume running the previous program.



4. Press 1 button on the keyboardinto waiting to send program state, and then select "send



5. Select the new edition total station software, click on "send"





6. It will display the sending application process, and then close the super terminal, starting up after removing theinstrument battery and then putting in again. The current software is the new version updated previously.

#### 3. Checkout and calibration

The instrument at the factory has to undergo a rigorous inspection and correction, meeting the quality requirements. However, after long transport or environmental change, its internal structure will be some impact. Therefore, the new purchased instruments should be checked and calibrated before surveying to ensure the precision.

#### 3.1 Tube level





#### Checkout

Refer to the chapter "Leveling instrument accurately by tubelevel" of "Setting up theinstrument"

#### Calibration

- 1. In the calibration, if the leveling bulbs diverge from the center, use the foot spiral which parallels the leveling tube to adjust to make the bubble move half of the distance to the center. For the remaining, use the calibration needle to turn the level calibration screw (in the right of the water-level) to adjust the bubble to the center.
- 2. Turn the instrument for 180°, check that whether the bubble is in the center. If the bubble is not centered, repeat Step (1) until the bubble to the center.
- 3. Turn the instrument for 90°, use the third foot screw to adjust the bubble to the center.
- Repeat the Steps of checkout and calibration until the bubble in the center in every direction.

#### 3.2 Circular level

#### Checkout

After the level tube calibrated correct, if the circular level bubble also in the center, so there is no need to calibrate

#### Calibration


If the bubbles is not in the center, use the correction needle or six angle wrench to adjust the correction screw which under the bubble to make the bubble to the center. For calibration, you shall first loosen the calibration screw (1 or 2) which opposite to the direction of the bubble offset, then tighten the other correction screw in the offset direction to make the bubble in the center. When the bubble is in center, make sure the pressures of the three calibration screws are consistent.

#### 3.3 Telescope reticle

#### Checkout


After leveling the instrument find a target A with the telescope, make the center of the crosshair focused on target A and fixed horizontal and vertical brake handwheel.

- 1. Rotate telescope vertical micrometer handwheel, move A point to the edge of the field of view (A 'points).
- 2. If A moves along the vertical line of the crosshair, but A point is still in the vertical line, as the left picture, the crosshair doesn't need to calibrate. If A point deviate from vertical line center, as the right pictured, the crosshair is slant, so need to calibrate the reticle.



#### Calibration

- 1. First, take down the reticle cover between telescope eyepiece and focusing handwheel, and you can see four fixed screw of the reticle bed (sees attached figure).
- 2. Unscrew the three fixed screw evenly with screwdriver, rotate the reticle around collimation axis, to make A point on the vertical line of the reticle.
- 3. Tighten the screw evently, test the calibration results with the above methods.
- 4. Put the protective cover back.



# 3.4 The verticality of collimation axis and horizontal axis(2C)

#### Checkout

- 1. Set a target A in about 100m away, and make sure the vertical angle of the target is within  $\pm$  3°. Precisely level the instrument and switch on it.
- 2. Make the telescope focused on target A in face left, and read the horizontal angle.

For example: horizontal Angle L = 10°13 '10".

Loosen the vertical and horizontal brake handwheel, turn the telescope, rotate
the alidade to face right and focus on the same target A. Before aiming please
tighten the horizontal and vertical brakehandwheel and read the horizontal
angle.


For example: level Angle R = 190°13 '40".

4. 2 C = L-(R  $\pm$ 180°) = -30 " $\geq$  $\pm$ 20, need to calibrate.

#### Calibration

1. Use the horizontal micrometer handwheel to adjust the horizontal angle to the right reading which has eliminated the C.

- 2. Take down the reticle bed cover between the telescope eyepieces and focusing handwheel, adjust the calibration screw of the crosshair on the left and right. First, loosen the screw on one side, and screw up the screw on the other side, move the reticle and focus on target A.
- 3. Repeat the test Steps, calibrate it to | 2 C | < 10.
- 4. Tighten the calibration screws, put the protective cover back.



Notice: Check the photoelectric coaxiality after calibrating.

# 3.5 Vertical plate index zero automatic compensation

#### Checkout

- 1. Set up and level the instrument, make the direction of the telescope consistent with the line between the center of the instrument and any of the foot screw.
- 2. The vertical plate index change to zero after switching on, tighten the vertical brake handwheel, the instrument display the current telescope vertical angle.
- 3. Slowly rotate feet X to 10 mm around in one direction, the display of the vertical Angle will change from changing until disappear to appear "compensation beyond!" correspondingly, it indicate that the dip angle of the verticalaxis is bigger than 3', beyond the range of vertical plate compensator design .When rotating the feet spiral recovery in the opposite direction, instruments shows vertical Angle again, if you can see the change when testing it again and again in critical positions, it says that vertical plate compensator works normally.

#### Calibration

When you find that instrument compensation is useless or abnormal, it should be sent to the factory for checking.

# 3.6 Vertical collimation error (I Angle) and vertical collimation zero value setting

#### Checkout

1. Boot after settling and leveling the instrument, focus the telescope on a clear goalA, get the face left reading of vertical Angle L.

- 2. Turn the telescope to aim A and get the reading R for face right.
- 3. If the vertical zenith angle is 0 °, then i = (L + R-360 °) / 2, if the vertical Angle level is 0. Then i = (L + R-180 °) / 2 or (L + R-540 °) / 2.
- 4. If  $|i| \ge 10$ ", may be you need reset the zero value of vertical index.
- 5. Operation refers to chapter "Adjust index error". Note: repeat the checkout steps to retest the index error again (i Angle). If the index error still can not accordance with requirements, it should check the three Steps of calibration index zero setting (in the course of zero setting, the vertical angle showed is not compensated and corrected, it is just for reference) to see whether it is incorrect, whether the focusing of target is correct, reset according to the requirements.
- 6. If it still can not accordant with the requirements after repeated operation, it should be sent to the factory for checking.


#### 3.7 Plummet

#### Checkout

- 1. Set up the instrument to the tripod, draw a cross on a white paper and put it on the ground below the instrument.
- 2. Adjust the focal length of the optical plummet (for the optical plummet) or switch on laser plummet, move the white paper to make the cross in the center in the field of view (or laser flare).
- 3. Turn the feet screw, make the center mark of the plummet coincide with the cross center.
- 4. Rotate alidade, every turn of 90 °, observe the contact ratio of the optical plummet and cross center.
- 5. When rotate the alidade, the center of the optical plummet always coincide with the cross center, there is no need to calibrate. Otherwise you should calibrate as the following methods.

#### Calibration

- 1. Take down the screw cover between the optical plummet eyepiece and the focusing handwheel.
- 2. Fix the white paper with a cross, and mark the points when the instrument rotates 90 °, as the figure shows A, B, C, D points.
- 3. Connect the diagonal points A、C and B、D with a straight line, the intersection name of the two line is O.
- 4. Use the calibration needle to adjust the four calibration screw, to make the center mark of the plummet coincide with point O.



- 5. Repeat Step 4, check and calibrate until it meet therequirements.
- 6. With the laser plummet, unbolt the laser cover, using 1 # hex wrench to adjust the three screws, fasten one side and loosen the other side, and adjust the laser flare to point O.
- 7. Put the cover back in place.

#### 3.8 Instrument additive constant (K)

The instrument constant is inspected when it out, and correct it inside the machine, make K = 0. Instrument constant change rarely, but we suggest that check it this way for one or two times each year. The checkout should be done in the standard baseline, or you can take the following simple method.

#### Checkout

- Choose a flat field A to set up and level the instrument, mark three points A、B、C in the same line, their interval is 50m, and set up the reflection prism accurately.
- 2. After setting the temperature and pressure data, accurately measure the horizontal distance of AB, AC.
- 3. Setting up and centering the instruments accurately, measure the horizontal distance of BC accurately.
- 4. You can get the instrument ranging constant:

$$K = AC-(AB + BC)$$

K should be close to 0, if | K | > 5 mm, it should be send to standard baseline field for strict checking, then calibrate it based on the checking value.

#### Calibration

If it turns out the instrument constant does not close to 0 but changing after strict inspection, you need to calibrate it, set the instrument additive constant according to the comprehensive constant K value. Such as: the K has been measured as -5 according to the method above, and the original instrument constant is -20,so the new value should be set as -20-(5) =-15; Input-15 through "menu-> 6-> 3" and then confirm .

- ➤ Use the vertical line of the reticle to orientate, make A, B and C at the same line accurately. There must be a clear mark for point B the ground to focus on.
- ➤ Whether the prism center of B coincide with the instrument centers is the guarantee of checking the accuracy, so, you had better use tripod and all-purpose tribrach, for example, if you change the three hand type prism connector with tribrach, keep the tripod and tribrach stable, just change the prism and the part above tribrach of instrument, and it can reduce the error of misalignment.

#### 3.9 The parallelism of collimation axis and photoelectricity axis

#### Checkout

1. Set up the reflecting prism 50 meters long from the instrument.

- 2. Focus on the reflecting prism center with telescope crosshair accurately.
- 3. Open EDM signal, observe maximum value of the signal, and find the center of the launch axis.
- 4. Check whether the telescope crosshair center coincide with the emission photoelectricity axis center, if they coincide on the whole we can say it qualified.

#### Calibration

If the telescope crosshair center deviates from emission photoelectricity axis center largely, send it to professional repair and calibration department.

### 3.10 No prism ranging

The red laser beam is coaxial with the telescope, used for no prism ranging, and it is sent by telescope. If the instrument has been calibrated, red laser beams will coincide with the line of sight. External influence such as the vibration, the larger temperature change and other factors may make laser beam and viewing not overlap.

➤ Before precise ranging, you should check whether the direction of the laser beam is coaxial. Otherwise, it could lead to inaccuracy.

#### Warning:

Looking straightly at the laser is dangerous.

#### **Prevention:**

Don't look laser beams directly, or focus on others.

#### Checkout

Put the gray side of the reflector towards the instrument, and put it 5 meters and 20 meters away. Start laser direction function. Focus on the reflector center by the telescope crosshair center, and then check the position of the red laser point. Generally speaking, the telescope is equipped with special filter, human eyes cann't see laser point through the telescope, you can see the offset between the red laser point and the reflector crosshair center, you can observe this above the telescope or at the side face of reflector. If laser center coincide with the crosshair center, it indicate that the adjustment meet required accuracy. If the offset between the pointsposition and the mark of crosshair is out of limitless, it need to send it to professional department for adjustment.

# 10. Technical parameters

Function		T. 1	Configuration	
		Unit	HTS-420R	
Imaging			_	Erect
	Magnification		×	30
Telescope	Field of view		_	1 °20′
	Min.target dis	tance	m	1.5
	Effective aper	ture	mm	40/50(EDM)
	2C index erro	•	(")	1.4
Angle	Angle i index	error	(")	2.0
measurement (Hz, V)	Angle measur	ement method	_	Absolute encoder
,	Minimum reading		(")	1
		Single prism	km	3
	Range	Triple prism	km	5
		No- prism1	m	400
Distance measurement	Time	Repeated	S	2(first 3)
(IR)		Tracking	S	0.8
	Minimum display		mm	0.1
		Prism		±(2+2×10 <sup>-6</sup> D)
	Accuracy	No- prism	mm —	±(3+2×10 <sup>-6</sup> D)
Tilt compensator	Compensation	n method		Biaxial type
·	Compensation range		(')	±3
Communication Port			_	RS232C
U disk interface			Yes	
Bluetooth		_	Yes	
Temperature and pressure sensor			No	
SD card		_	Yes	

Display	Screen			Both sides (280*160, Black and white screen)	
	Illumination		_	Support	
Laser Plumb	Laser (optional) Laser Plumb		_	Wavelength 635nm Maximum output power (adjustable): not less than 0.4 m W, not more than 1.0 m W	
Level	Tubular level		( " ) /2 mm		
	Round level		(')/2 mm	8	
Built-in application	Built-in application			Support	
	Туре		_	Rechargeable High-energy lithium battery	
	Voltage		V	7.4	
Battery supply	Power		W	< 2.2	
	Battery capacity		mAh	3000	
	Working	Angle	h	18	
	duration Dist+Angle	h	8 (At + 20 ° C, constant measuring mode)		

1: Refers to good weather conditions (visibility is not less than 30km), the goal of KODAK CAT NO.E1527795 (90% of reflecting surface)

# 11. Attachment A Road calculation example

# Horizontal Curve

#### 1.Element

# (1)Input elements

NO.	Element	Start X	Start Y	Azimuth	Length	Radius
1	Line	1099877.123	4578452.654	120.30250	88.12	
2	Tran.Curve				100	200
3	Circular Curve				80	200
4	Tran.Curve				50	200
5	Tran.Curve				45	-150
6	Circular Curve				125	-150
7	Tran.Curve				62	-150
8	Line				30	

# (2)Calculate Middlepile coordinate interval: 25 Calculated value

NO.	Pile	X	Y
1	0.000	1099877.123	4578452.654
2	25.000	1099864.432	4578474.193
3	50.000	1099851.741	4578495.732
4	75.000	1099839.050	4578517.272
5	88.120	1099832.390	4578528.575
6	100.000	1099826.347	4578538.804
7	125.000	1099813.310	4578560.134
8	150.000	1099799.305	4578580.839
9	175.000	1099783.746	4578600.395
10	188.120	1099774.794	4578609.984
11	200.000	1099766.173	4578618.155
12	225.000	1099746.535	4578633.600
13	250.000	1099725.125	4578646.476
14	268.120	1099708.688	4578654.087
15	275.000	1099702.279	4578656.588
16	300.000	1099678.498	4578664.280

17	318.120	1099661.029	4578669.092
18	325.000	1099654.388	4578670.891
19	350.000	1099630.474	4578678.158
20	363.120	1099618.263	4578682.949
21	375.000	1099607.584	4578688.147
22	400.000	1099586.640	4578701.745
23	425.000	1099568.243	4578718.630
24	450.000	1099552.901	4578738.333
25	475.000	1099541.041	4578760.307
26	488.120	1099536.325	4578772.546
27	500.000	1099532.962	4578783.937
28	525.000	1099528.087	4578808.446
29	550.000	1099524.876	4578833.238
30	550.120	1099524.862	4578833.357
31	575.000	1099521.947	4578858.066
32	580.120	1099521.347	4578863.151

# 2. Intersection

# (1)Input element

NO.	Х	Υ	A1	Radius	A2	Mileage
1	126595.622	326532.868				
2	127029.195	328544.441	711.09	2528.248	711.09	2057.769
3	126270.297	330165.767	550.05	2017.0340	0	0
4	126797.134	331957.950	0	1699.1193	504.844	0
5	129306.674	332294.008	636.169	2023.5527	550.938	0
6	130014.424	334370.388	0	0	0	0

# $(2) \textbf{Calculate Middle pile coordinate Interval:} \quad \textbf{500}$

# Calculated value

NO.	Pile	Х	Υ
1	0.000	126595.622	326532.868
2	500.000	126700.972	327021.643
3	1000.000	126806.322	327510.418
4	1105.563	126828.565	327613.611
5	1305.563	126868.121	327809.646

1500.000	126894.146	328002.286
2000.000	126892.623	328501.469
2500.000	126793.052	328990.623
2749.107	126707.910	329224.621
2949.107	126625.526	329406.849
3000.000	126604.016	329452.973
3099.107	126563.629	329543.472
3500.000	126444.885	329925.686
4000.000	126406.074	330422.894
4483.815	126485.817	330898.918
4500.000	126490.455	330914.423
5000.000	126703.815	331364.622
5500.000	127038.580	331733.585
6000.000	127465.969	331989.592
6365.804	127816.349	332092.209
6500.000	127949.036	332112.201
6515.804	127964.700	332114.301
6516.206	127965.099	332114.355
6716.206	128162.844	332144.159
7000.000	128437.402	332215.044
7500.000	128887.275	332430.323
8000.000	129270.830	332749.096
8500.000	129564.769	333151.998
8785.668	129685.352	333410.708
8935.668	129735.494	333552.069
9000.000	129756.249	333612.961
9500.000	129917.564	334086.224
9800.219	130014.424	334370.388
	2000.000 2500.000 2749.107 2949.107 3000.000 3099.107 3500.000 4000.000 4483.815 4500.000 5000.000 5000.000 6365.804 6500.000 6515.804 6516.206 6716.206 7000.000 7500.000 8000.000 8500.000 8785.668 8935.668 9000.000	2000.000       126892.623         2500.000       126793.052         2749.107       126707.910         2949.107       126625.526         3000.000       126604.016         3099.107       126563.629         3500.000       126444.885         4000.000       126406.074         4483.815       126485.817         4500.000       126703.815         5500.000       127038.580         6000.000       127465.969         6365.804       127816.349         6500.000       127949.036         6515.804       127964.700         6516.206       127965.099         6716.206       128162.844         7000.000       128437.402         7500.000       129270.830         8500.000       129564.769         8785.668       129685.352         8935.668       129735.494         9000.000       129917.564

# Theoretical value

NO.	Pile	х	Υ
1	0.000	126595.622	326532.868
2	500.000	126700.972	327021.643
3	1000.000	126806.323	327510.419
4	1105.563	126828.565	327613.611
5	1305.563	126868.121	327809.646
6	1500.000	126894.146	328002.286
7	2000.000	126892.623	328501.469

8	2500.000	126793.051	328990.623
9	2749.107	126707.910	329224.621
10	2949.107	126625.526	329406.849
11	3000.000	126604.016	329452.974
12	3099.107	126563.629	329543.472
13	3500.000	126444.885	329925.686
14	4000.000	126406.074	330422.895
15	4483.815	126485.817	330898.918
16	4500.000	126490.455	330914.424
17	5000.000	126703.815	331364.622
18	5500.000	127038.580	331733.585
19	6000.000	127465.969	331989.592
20	6365.804	127816.349	332092.209
21	6500.000	127949.037	332112.201
22	6515.804	127964.700	332114.301
23	6516.206	127965.099	332114.355
24	6716.206	128162.844	332144.159
25	7000.000	128437.402	332215.044
26	7500.000	128887.275	332430.323
27	8000.000	129270.830	332749.096
28	8500.000	129564.769	333151.999
29	8785.668	129685.352	333410.708
30	8935.668	129735.494	333552.069
31	9000.000	129756.249	333612.961
32	9500.000	129917.564	334086.224
33	9800.219	130014.424	334370.388

# Vertical Curve

# Input Intersection

Intersectio	Mileage	Elevation	Length
n	Of Slope changing PT	of Slope changing PT	
Start	0	324.325	0
1	508.36	329.247	84.560
2	1000.48	325.689	52.806
3	1320.236	320.563	120.000
4	1524.265	323.215	28.585
5	1699.888	324.585	31.445
End	1800.244	325.999	0

# Piles elevation

NO.	Mileage (Pile)	Calculated	Theoretical
		Value	Value
1	0.000	324.325	324.325
2	100.000	325.293	325.293
3	200.000	326.261	326.261
4	300.000	327.230	327.230
5	400.000	328.198	328.198
6	500.000	329.051	329.051
7	600.000	328.584	328.584
8	700.000	327.861	327.861
9	800.000	327.138	327.138
10	900.000	326.415	326.415
11	1000.000	325.636	325.636
12	1100.000	324.094	324.094
13	1200.000	322.490	322.491
14	1300.000	321.079	321.079
15	1400.000	321.600	321.600
16	1500.000	322.900	322.900
17	1600.000	323.806	323.806
18	1700.000	324.611	324.611
19	1800.000	325.996	325.996
20	1900.000	0.000	0.000
21	2000.000	0.000	0.000
22	2100.000	0.000	0.000

# 12. Attachment B File format introduction

These following example to instruct exported file format:

STAST001,1.205,AD

XYZ 100.000,100.000,10.000 BKB BS001,45.2526,50.0000

BS BS001,1.800

HVD98.2354,90.2314,10.235

SC A1,1.800,CODE1

NEZ 104.662,99.567,10.214

SD A2,1.800,CODE1

HVD 78.3628,92.4612,4.751

SA A3,1.800,CODE1 HV 63.2349,89.2547

NOTE this note

The first record consists of two lines:

The information of first line: record type, name, elevation, code

Such as:

STA refers to test site

BKB refers to back sight Angle data

BS refers to back sight

SC refers to coordinate data

SD refers to distance measurement data
SA refers to Angle measurement data

The second line information: data types, data records

Such as:

NEZ refers that the following data are coordinates

ENZ refers that the following data are coordinates

HVD refers thatthe following data are horizontal Angle and vertical Angle and

slope distance

HV refers that the following data are horizontal Angle and vertical Angle

